				Regione	Valle d'Aosta	Piemonte	Liguria	Lombardia	Veneto	Trentino Alto Adige	Friuli Venezia Giulia	Emilia Romagna	Toscana	Lazio	Marche	Abruzzo	Umbria	Molise	Campania	Basilicata	Puglia	Calabria	Sicilia	Sardegna	ATTREZZATURE																									
				Sede regionale	Non presenti	Scarmagno (TO)	Genova	Sesto San Giovanni (MI)	Vicenza	Lana	Udine	Bologna	Pisa	Roma	Ancona	Chieti	Terni	Termoli	Napoli	Potenza	Bari	Rende (CS)	Fiumefreddo (CT)	Quartu S'Elena (CA)	GRUPPO SC					GRUPPO SP					GRUPPO GVR													
Verificatori				Qualifiche		SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	SC SP GVR	a	b	c	d	e	a	b	c	d	e	f	a1	a2	a3	a4	a5	a6	b					
1	ing.	Raffaelli Giovanni	2	SC-SP-GVR		SC-SP-GVR																			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
2	p.i.	Papponetti Mario	2	SC - GVR			GVR-SC																		x	x	x	x	x						x	x	x	x	x	x	x					
3	ing.	Murchio Aldo	2	SP			SP																		x	x	x	x			x	x		x	x											
4	ing.	Spicchiarello Marco	1	SC				SC																	x	x	x	x	x																	
5	p.i.	Locatelli Fabio	1	GVR				GVR																											x	x	x	x	x	x	x					
6	ing.	Adani Umberto	1	SP				SP																						x	x	x	x	x	x											
7	ing.	Cantali Alessandro	2	SP					SP																					x	x	x	x	x	x											
8	p.i.	Piva Marco	2	GVR -SC					GVR-SC																x	x	x	x	x						x	x	x	x	x	x	x					
9	ing.	Favero Adriano	2	GVR						GVR															x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
10	ing.	De Meo Adolfo	2	SC						SC															x	x	x	x	x																	
11	ing.	Panero Marco	2	SP						SP																				x	x	x	x	x	x											
12	ing.	Zanetti Tiziana	2	GVR - SC - SP							GVR-SC - SP														x	x	x	x	x	x	x	x	x	x	x	X											
13	ing.	Bovi Gilberto	1	GVR							GVR																									x	x	x	x	x	x	x					
14	ing.	Sauro Mirko	2	SC-SP								SP-SC													x	x	x	x	x	x	x	x	x	x	x											
15	ing.	Santacroce Giuseppe	2	GVR								GVR																								x	x	x	x	x	x	x					
16	ing.	Iovacchini Massimo	2	GVR									GVR																							x	x	x	x	x	x	x					
17	ing.	Corbo Domenico	2	SC - SP									SC - SP												x	x	x	x	x	x	x	x	x	x	x											
18	ing.	Altavilla Fausto	2	SC - GVR - SP										SC-GVR-SP											x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
19	p.i.	Ciferri Stefano	2	SC - GVR											SC-GVR										x	x	x	x	x							x	x	x	x	x	x	x					
20	ing.	Tomaiuoli Enrico	2	SP											SP															x	x	x	x	x	x											
21	ing.	Scarpa Stefano	2	SC - GVR												SC-GVR									x	x	x	x	x							x	x	x	x	x	x	x					
22	ing.	Rubbo Giancarlo	2	SP												SP														x	x	x	x	x	x											
23	ing.	Melchiorre Donato Antonio	2	GVR													GVR																			x	x	x	x	x	x	x					
24	ing.	Malatesta Fabio	2	SC-SP													SC-SP								x	x	x	x	x	x	x	x	x	x	x											
25	ing.	Malatesta Costantino	2	SP-SC														SP-SC							x	x	x	x	x	x	x	x	x	x	x											
26	p.i.	De Martino Gerardo	2	GVR														GVR																		x	x	x	x	x	x	x					
27	ing.	Serena Carlo	2	SC															SC						x	x	x	x	x																	
28	ing.	Baesse Moreno	2	SP															SP											x	x	x	x	x	x											
29	ing.	Di Gesu Ignazio	2	GVR															GVR																	x	x	x	x	x	x	x					
30	p.i.	Dell'Osso Angelo	2	SP-SC - GVR																SP-SC - GVR					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
31	ing.	Vitale Elvio	2	SC - SP - GVR																	SC - SP - GVR				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
32	ing.	Greco Eugenio	2	SC - SP																		SP - SC			x	x	x	x	x	x	x	x	x	x	x											
33	ing.	Napolitano Marco Pasquale	2	GVR																		GVR													x	x	x	x	x	x	x					
34	ing.	Caramagno Francesco	2	SP																			SP							x	x	x	x	x	x											
35	ing.	Fontana Carlo	2	GVR																			GVR													x	x	x	x	x	x	x					
36	ing.	Pinizzotto Roberto	2	SC																			SC		x	x	x	x	x																	
37	ing.	Ajossa Sergio	2	SP																				SP						x	x	x	x	x	x											
38	ing.	Serra Massimo	2	SC - GVR																				SC - GVR	x	x	x	x	x							x	x	x	x	x	x	x					
39	p.i.	Battello Luigi	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
40	ing.	Blancato Sebastiano	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
41	ing.	D'Elia Filippo	2	GVR																GVR	GVR	GVR														x	x	x	x	x	x	x					
42	p.i.	Di Giacomi M.	1	GVR-SC		GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	x	x	x	x	x							x	x	x	x	x	x	x					
43	ing.	Favero Adriano	1	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
44	ing.	Fini Nicola	2	GVR-SC		GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC	GVR-SC			x		x							x	x	x	x	x	x	x					
45	ing.	Mannelli Domenico	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR													x	x	x	x	x	x	x					
46	p.i.	Piva Arduino	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
47	p.i.	Piva Giovanni	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
48	p.i.	Scapillati Giuseppe	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												X	X	X	X	X	X	X					
49	ing.	Siddi Filippo	1	GVR - SC - SP		GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	x	x	x	x	x		x	x				x	x	x	x	x	x	x					
50	ing.	Spicchiarello Marco	1	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
51	ing.	Tenaglia Ciro	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
52	ing.	Zura Puntaroni Giovanni	2	GVR		GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR	GVR												x	x	x	x	x	x	x					
54	ing.	Murchio Aldo	2	SC		SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	x	x	x	x																	
55	ing.	Fazio Gaspare	2	SC		SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	x		x	x																	
56	ing.	Capinteri Giuseppe	2	SC		SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	x		x	x																	
57	ing.	Rega Francesco	2	SC		GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	GVR - SC-SP	x	x	x	x	x		x	x				X	X	X	X	X	X	X					
58	ing.	Santacroce Giuseppe	2	SC		SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	SC	x	x	x	x	x																	
TOTALE ISPETTORI PER REGIONE						19	20	21	20	21	21	21	20	19	20	20	20	20	21	20	20	21	21	19																							

Ing. Filippo Siddi Responsabile tecnico (1); **Ing. Marco Spicchiarello Sostituto responsabile tecnico (1)**