

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	比利時 (Belgium)	<p>品牌(Brand) : Homday 品名(Name) : 電鍋 (Rice cooker) 型號 (Model) : 622850</p>	<p>電飯煲底部在使用過程中容易脫落，導致帶電部件觸及。用戶可能接觸到帶電部件並遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60335 的要求。 The bottom of the rice cooker can easily detach during use, making live parts accessible. The user can touch the live parts and receive an electrical shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
13	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand) : Snuggla 品名(Name) : 電熱毯 (Electric blanket) 型號 (Model) : HT-65180-SN</p>	<p>該產品在使用過程中容易過熱。過熱可能導致塑膠電纜蓋熔化，從而引發火災並燙傷用戶。 該產品不符合低電壓指令的要求。 The product is prone to overheating whilst in use. The overheating can cause the plastic cable cover to melt, resulting in a fire and causing burns to the user. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>終端使用者手中召回產品 Recall of the product from end users</p>	
13	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand) : Trade Fittings Direct 品名(Name) : 插頭 (Electric plug) 型號 (Model) : 不詳 (unknown)</p>	<p>插頭插腳可能會斷裂並殘留在插座中，如果使用者試圖拔出插頭，則會增加觸電風險。此外，由於插頭保險絲存在缺陷，產品可能會過熱熔斷，從而產生火花，引發火災。 該產品不符合低電壓指令的要求。 The plug pins can break and remain in the socket outlet, increasing the risk of electric shock if the user tries to remove it. Moreover, due to a plug's fuse defect, the product can overheat and melt, which can provoke a spark that can cause a fire. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：寵物籠子 (Pet cage) 型號 (Model)：不詳 (unknown)	<p>說明書中沒有充分提到如何將電線放在寵物籠內，避免寵物接觸到。如果寵物被放在籠內無人看管，並且接觸到加熱墊的電線，它們可能會咬斷電線，導致觸電。此外，加熱散熱器沒有防護裝置，寵物很容易接觸到高溫表面。此外，產品附帶的溫度和濕度指示器存在窒息危險。此外，其鈕扣電池很容易接觸到，可能導致寵物體內灼傷。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The instructions are inadequate in relation to keeping wires out of reach of the pets in the crate. If a pet is placed in the crate and left unsupervised, and the wire for heating the pad is accessible to them, they may bite through the wires, leading to an electric shock. Moreover, the heating radiators are not guarded, leaving hot surfaces accessible to the pet. Additionally, the supplied temperature and humidity indicating device presents a choking hazard. Further its button batteries are easily accessible and can lead to internal burns to the pet.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	邊境拒絕進口 Import rejected at border	
15	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：Youngine 品名(Name)：花園燈 (Garden light) 型號 (Model)：不詳 (unknown)	<p>該產品的電線固定不足，導致使用時產品端子承受過大壓力。這可能導致端子失效並過熱，從而引發火災。此外，該產品使用的電源線不適合戶外使用，電源插頭的尺寸也不合適。用戶可能接觸到可觸及的帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The product has insufficient cord anchorage, leading to strain on the terminals of the product when in use. This could cause the termination to fail and overheat, causing a fire. Additionally, the product is powered using a cord that is inappropriate for outdoor use, and the dimensions of the mains plug are inappropriate. The user can touch accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	邊境拒絕進口 Import rejected at border	



2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
15	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : Bauer 品名(Name) : 電熱水袋 (Electric hot water bottle) 型號 (Model) : CHB-006	插頭安裝的保險絲不正確 (13 安培, 而非 3 安培)。該保險絲可能允許過大的電流通過, 導致產品過熱並存在潛在的火災風險。 該產品不符合低壓指令的要求。 The plug is fitted with an incorrect fuse (13-amp instead of 3-amp). This fuse can permit excessive current flow, resulting in the product overheating and the potential risk of fire. The product does not comply with the requirements of the Low Voltage Directive.	警告消費者風險 Warning consumers of the risks	
13	立陶宛 (Lithuania)	品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 3033	該產品電氣絕緣不足, 可能導致用戶觸電。 該產品不符合低壓指令的要求, 也不符合歐洲標準 EN 60598。 The product's electrical insulation is inadequate, which can lead to the user receiving an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	
13	立陶宛 (Lithuania)	品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 3033	該產品電氣絕緣不足, 可能導致用戶觸電。 該產品不符合低壓指令的要求, 也不符合歐洲標準 EN 60598。 The product's electrical insulation is inadequate, which can lead to the user receiving an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	立陶宛 (Lithuania)	<p>品牌(Brand)：OKKO 品名(Name)：電源延長線 (Extension cord) 型號 (Model)：KF-Y5-01P</p>	<p>該產品的插座沒有保護蓋，導致帶電部件容易接觸。用戶可能接觸到這些帶電部件並遭受電擊。 該產品不符合低電壓指令的要求。 The socket of the product does not have protective covers, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
14	立陶宛 (Lithuania)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：2536</p>	<p>電氣絕緣不足。花環控制裝置的蓋子很容易被打開，從而暴露帶電部件。因此，用戶可能觸電。 該產品不符合低壓指令和歐洲標準 EN 60598。 The electrical insulation is inadequate. The cover of the garland control device can be easily removed, thus exposing live parts. As a result, the user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
15	匈牙利 (Hungary)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：SDD-XHWX</p>	<p>電纜固定不當，可觸及電線絕緣不足。此外，該產品未採用防潮保護，但建議在戶外使用。水可能會滲入產品，或使用者可能接觸可觸及帶電部件並遭受電擊。 該產品不符合低壓指令和歐洲標準 EN 60598。 The cable is not properly anchored and the accessible wires have inadequate insulation. Moreover, the product is not protected against moisture but is recommended for outdoor use. The water could penetrate the product or the user could touch the accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	西班牙 (Spain)	<p>品牌(Brand) : Luz Europa 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 35007</p>	<p>電線直徑太小，可能導致熱量積聚，從而導致產品起火和/或燙傷用戶。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60598。 The diameter of the wire is too small, which could lead to heat being accumulated and cause the product to catch fire and/or cause burns to users. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
13	西班牙 (Spain)	<p>品牌(Brand) : XING GUANG 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 51001</p>	<p>電線直徑太小，可能導致熱量積聚，從而導致產品起火和/或燙傷用戶。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60598。 The diameter of the wire is too small, which could lead to heat being accumulated and cause the product to catch fire and/or cause burns to users. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
14	西班牙 (Spain)	<p>品牌(Brand) : Tengda 品名(Name) : 電源延長線 (Extension cord) 型號 (Model) : 33115</p>	<p>由於連接器蓋未牢固固定，控制裝置中的帶電部件容易被觸及。用戶可能觸及可觸及的帶電部件並遭受電擊。此外，電纜橫截面積過小，容易發熱，造成火災和燙傷風險。 該產品不符合低壓指令和歐洲標準 EN 60598。 The live parts in the control device can be accessed since the connector cover is not securely fastened. The user could touch the accessible live parts and receive an electric shock. Moreover, the cross-section of the cable is too small, hence heating up easily and creating a risk of fire and burns for the user. The product does not comply with the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	西班牙 (Spain)	品牌(Brand) : DICTROLUX 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 405868 405869 405870 40587OR	電線截面積太小，可能導致電線過熱，從而引發火災和/或燒傷。 該產品不符合低電壓指令的要求。 The cross-sectional area of the wires is too small, which can cause them to overheat, leading to fire and/or burns. The product does not comply with the requirements of the Low Voltage Directive.	禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures	
14	西班牙 (Spain)	品牌(Brand) : Tengda 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : YF-D6065	該產品的電線直徑不足，因此容易發熱，造成火災和燙傷風險。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60598。 The wire of the product has an insufficient diameter, hence heating up easily and creating a risk of fire and burns for the user. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures	
14	法國 (France)	品牌(Brand) : PI DESIGN 品名(Name) : 旅行適配器 (Travel adaptor) 型號 (Model) : CHU468	產品的帶電部件在使用過程中容易接觸。用戶可能接觸到這些部件並遭受電擊。 該產品不符合低電壓指令的要求。 The live parts of the product become accessible during use. The user could touch them and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	法國 (France)	<p>品牌(Brand) : CONFORT ZONE 品名(Name) : 電動按摩腰帶 (Electric massage belt) 型號 (Model) : 15210890</p>	<p>產品表面溫度非常高 (測量值為 39 K 至 53 K, 相當於比室溫高出 39°C 至 53°C), 可能導致用戶燙傷。 該產品不符合低壓指令和歐洲標準 EN 60335 的要求。 The surface of the product becomes very hot (measured value from 39 K to 53 K, equivalent to 39°C to 53°C above room temperature), which may cause burns to the user. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
15	法國 (France)	<p>品牌(Brand) : KD EUROPE 品名(Name) : 電池和充電器 (Battery and charger) 型號 (Model) : S039-A XQH-420S020</p>	<p>即使超出其工作溫度範圍, 電池也不會停止充電。這可能導致電池過熱並起火。 該產品不符合機械指令和通用產品安全法規的要求。 The battery does not stop charging even when it is beyond the range of its operating temperature. This can cause the battery to overheat and catch fire. The product does not comply with the requirements of the Machinery Directive nor with the General Product Safety Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
13	芬蘭 (Finland)	<p>品牌(Brand) : Dudao 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : A8SEUC</p>	<p>一次電路和可觸及二次電路以及變壓器絕緣之間的電氣間隙和爬電距離不足。用戶可能接觸帶電部件並遭受電擊。 該產品不符合低壓指令和歐洲標準 EN 62368 的要求。 The clearance and creepage distance between the primary and accessible secondary circuits and the transformer insulation are not sufficient. The user can access live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368.</p>	<p>終端使用者手中召回產品 Recall of the product from end users</p>	
15	芬蘭 (Finland)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 電源 (Power supply) 型號 (Model) : SJT-180E</p>	<p>帶電初級部件與輸出直流連接器之間的絕緣不足。用戶可能接觸帶電部件並遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60335 的要求。 The insulation between the live primary parts and the output DC connector is not adequate. The user can access live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor the European standard EN 60335.</p>	<p>終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
16	捷克 (Czechia)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：LAG-100LED Světelný řetěz</p>	<p>電源固定不當。用戶可能接觸可觸及帶電部件並遭受電擊。 該產品不符合低電壓指令的要求。 The power supply is not properly anchored. The user could touch the accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
15	愛爾蘭 (Ireland)	<p>品牌(Brand)：Sangamo 品名(Name)：連結裝置 (Connection units) 型號 (Model)：PSPBFB PSPBFS PPSF24 PPSF247 PPSF247B PPSF247S PPSF24B PPSF24S</p>	<p>帶保險絲計時器的外殼可能會變形，導致帶電部件觸及。用戶可能會觸電。此外，帶保險絲計時器的外殼可能會過熱熔化，從而導致灼傷和吸入煙霧。 該產品不符合低壓指令的要求。 The housing of the fused timer can deform leaving live parts accessible. The user may receive an electric shock. Moreover, the housing of the fused timer can overheat and melt resulting in potential burns and smoke inhalation. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 4 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：話筒 (Karaoke microphone) 型號 (Model)：858</p>	<p>產品中的焊料鎘含量超標 (測量值高達 0.23% (重量百分比))。電纜塑膠材質中鄰苯二甲酸二 (2-乙基己基) 酯 (DEHP)、鄰苯二甲酸二丁酯 (DBP) 和短鏈氯化石蠟 (SCCP) 的含量超標 (測量值分別高達 1.7%、1.2% 和 4.0% (重量百分比))。鎘具有生物累積性，對環境構成風險。鄰苯二甲酸酯對人類健康和環境構成風險。短鏈氯化石蠟在環境中持久存在，低濃度時對水生生物具有毒性，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長期通過皮膚接觸這些物質可能致癌。</p> <p>該產品不符合《限制在電氣和電子設備中使用某些有害物質的指令》(RoHS 2 指令) 的要求，也不符合《持久性有機污染物》(POP) 法規的要求。</p> <p>The solders in the product have an excessive concentration of cadmium (measured value: up to 0.23% by weight). The plastic material of the cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP) and short chain chlorinated paraffins (SCCPs) (measured values: up to 1.7%, 1.2% and 4.0% by weight, respectively). Cadmium bio-accumulates and poses a risk to the environment. The phthalate poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p>	不詳 (unknown)	



2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	瑞典 (Sweden)	<p>品牌(Brand) : QZT 品名(Name) : 攝像頭 (camera) 型號 (Model) : ps2-T01</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 52% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 52% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	
13	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 電動牙刷 (Electric toothbrush) 型號 (Model) : 不詳 (unknown)</p>	<p>該產品焊料中的鉛含量超標 (測量值: 按重量計高達 73%)。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value: up to 73% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
13	瑞典 (Sweden)	<p>品牌(Brand) : PowerPal 品名(Name) : 投影儀 (Projector) 型號 (Model) : WA1255</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 77% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 77% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	



2025 年 4 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：無線麥克風 (Wireless microphone) 型號 (Model)：不詳 (unknown)</p>	<p>產品中的焊料鉛含量超標 (測量值高達 48% (重量百分比))。電纜塑膠材質中鄰苯二甲酸二 (2-乙基己基) 酯 (DEHP)、鄰苯二甲酸二丁酯 (DBP)、短鏈氯化石蠟 (SCCP) 和鉛的含量超標 (測量值分別高達：1.0%、0.2%、0.97% 和 0.25% (重量百分比))。鉛對環境構成威脅。鄰苯二甲酸酯對人類健康和環境構成威脅。短鏈氯化石蠟在環境中持久存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成威脅。長期通過皮膚接觸這些物質可能致癌。</p> <p>該產品不符合《限制在電子電氣設備中使用某些有害物質指令》(RoHS 2.0) 和《持久性有機污染物 (POP) 法規》的要求。</p> <p>The solders in the product have an excessive concentration of lead (measured value up to 48% by weight). The plastic material of the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP), short chain chlorinated paraffins (SCCPs) and lead (measured values up to: 1.0%, 0.2%, 0.97% and 0.25% by weight, respectively). Lead poses a risk to the environment. The phthalates pose a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 4 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
13	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：兒童照相機 (Children's camera) 型號 (Model)：不詳 (unknown)</p>	<p>電纜塑膠材質中鄰苯二甲酸二 (2-乙基己基) 酯 (DEHP)、鄰苯二甲酸二丁酯 (DBP)、鉛和短鏈氯化石蠟 (SCCP) 的含量超標 (測得的含量分別高達 0.42%、1.6%、0.34% 和 1.7% (按重量計))。DEHP 和 DBP 對人體健康和環境構成威脅。鉛對環境構成威脅。SCCP 會持續存在於環境中，低濃度時對水生生物具有毒性，並在野生動物和人類體內生物累積，對人體健康和環境構成威脅。</p> <p>該產品不符合《限制在電子電氣設備中使用某些有害物質指令》(RoHS 指令) 和《持久性有機污染物 (POP) 法規》的要求。</p> <p>The plastic material of the cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP), lead and short chain chlorinated paraffins (SCCPs) (measured values up to 0.42%, 1.6%, 0.34% and 1.7% by weight, respectively). DEHP and DBP pose a risk to human health and the environment. Lead poses a risk to the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>線上市場/網店刪除該產品清單 Removal of this product listing by the online marketplace/webshop</p>	
14	義大利 (Italy)	<p>品牌(Brand)：GINMA 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：XN - 8123 XN - 8124</p>	<p>導線截面不足。這可能導致過熱並降低產品的堅固性。此外，如果發生短路，帶電部件可能會被觸及，從而導致觸電或引發火災。</p> <p>該產品不符合低壓指令和歐洲標準 EN 60598 的要求。</p> <p>The cross-sections of the conductors are insufficient. This can cause overheating and reduce the robustness of the product. Moreover, in the event of a short circuit, live parts can become accessible leading to electrocution or causing a fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025 年 4 月 電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	美國 (America)	品牌(Brand)：不詳 (unknown) 品名(Name)：可折疊旅行吹風機 (Foldable Travel Hair Dryers) 型號 (Model)：不詳 (unknown)	<p>掌上型吹風機缺乏浸水保護裝置，如果在插入電源時掉入水中，可能會因觸電或電擊危險而導致死亡或嚴重傷害。這些吹風機違反了聯邦法規，並存在嚴重的產品危害。</p> <p>The handheld hair dryers lack an immersion protection device that can cause death or serious injury due to electrocution or shock hazards if it falls into water when plugged in. The hair dryers are in violation of the federal regulations and present a substantial product hazard.</p>	退款 Refund	
14	美國 (America)	品牌(Brand)：不詳 (unknown) 品名(Name)：迷你旅行吹風機 (Mini Travel Hair Dryers) 型號 (Model)：不詳 (unknown)	<p>掌上型吹風機缺乏浸水保護裝置，如果吹風機在插入電源時掉入水中，可能會因觸電或電擊而導致死亡或嚴重傷害。這些吹風機違反了聯邦法規，並存在嚴重的產品危害。</p> <p>The handheld hair dryers lack an immersion protection device and can cause death or serious injury due to electrocution or shock if the hair dryers fall into water when plugged in. The hair dryers are in violation of the federal regulations and present a substantial product hazard.</p>	退款 Refund	
14	美國 (America)	品牌(Brand)：LVOE 品名(Name)：吹風機 (Hair Dryers) 型號 (Model)：X13	<p>掌上型吹風機缺乏浸水保護裝置，如果在插入電源時掉入水中，可能會因觸電或電擊而導致死亡或嚴重傷害。這些吹風機違反了聯邦法規，並存在嚴重的產品危害。</p> <p>The handheld hair dryers lack an immersion protection device and can cause death or serious injury due to electrocution or shock if they fall into water when plugged in. The hair dryers are in violation of the federal regulations and present a substantial product hazard.</p>	退款 Refund	

2025 年 4 月 電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
14	美國 (America)	<p>品牌(Brand) : Vivitar 品名(Name) : 攪拌瓶 (Blender Bottles) 型號 (Model) : ES15-BB-TA</p>	<p>當瓶子沒有連接到攪拌機上時，攪拌機的刀片仍會繼續運轉，從而造成割傷危險。 The blender's blades can continue to operate when the bottle is not attached to the blender, posing a laceration hazard.</p>	<p>退款 Refund</p>	
15	美國 (America)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 充電寶 (Power bank) 型號 (Model) : E33A</p>	<p>召回移動電源中的鋰離子電池可能過熱並起火，對消費者造成火災和燒傷危險。 The lithium-ion battery in the recalled power banks can overheat and ignite, posing fire and burn hazards to consumers.</p>	<p>替換 Replace</p>	

2025 年 4 月電子電氣產品召回案例 (亞太地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
15	澳大利亞 (Australia)	<p>品牌(Brand)：Powertech 品名(Name)：USB 電源適配器 (USB mains power adaptors) 型號 (Model)：MP3403；MP3406；MP3409</p>	<p>電源外殼可能會脫落，導致用戶接觸帶電部件。 如果消費者接觸帶電部件，可能會因觸電或觸電而導致嚴重受傷或死亡。 The outer casing of the power supply can come apart exposing the user to live parts. Risk of serious injury or death from electric shock or electrocution if consumers are exposed to live parts.</p>	<p>立即停止使用該產品。 將產品退回購買地點即可獲得全額退款。 Stop using the product immediately. Return the product to the place of purchase for a full refund.</p>	