


2025年8月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
32	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : Apple (counterfeit) 品名(Name) : USB-C 適配器 (USB-C power adaptor) 型號 (Model) : A1696 C3D0375A0ZVPDYNAR02	使用時，插頭插銷連接不牢固。這可能導致產品過熱並引發火災。此外，由於對帶電部件的防護不足，使用者在將插頭插入或拔出插座時可能會觸電。 本產品不符合低電壓指令的要求。 The plug pins do not connect securely when in use. This could cause the product to overheat and cause a fire. Moreover, the user can receive an electric shock when inserting or removing the plug from the socket as there is inadequate protection against the live parts. This product does not comply with the requirements of the Low Voltage Directive.	邊境拒絕進口 Import rejected at border	
32	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : JJINGRUI 品名(Name) : 牛奶攪拌機 (Milk mixer) 型號 (Model) : 不詳 (unknown)	該產品的保險絲顆粒填充不足。如果產品在使用過程中發生電氣故障，可能會起火或爆炸。 該產品不符合低電壓指令的要求。 The product's fuse has insufficient granular filler. If the product experiences an electrical fault whilst in use, it may catch fire or explode. The product does not comply with the requirements of the Low Voltage Directive.	邊境拒絕進口 Import rejected at border 產品銷毀 Destruction of the product	
33	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : Baoshishan 品名(Name) : 旋轉展示架 (Rotating display stand) 型號 (Model) : 不詳 (unknown)	該產品絕緣不足，導致帶電部件容易被觸及。用戶可能接觸到這些易觸及的帶電部件並遭受電擊。 該產品不符合低電壓指令的要求。 The product has inadequate insulation, which makes live parts accessible. The user could touch the accessible live parts and receive an electric shock. This product does not comply with the requirements of the Low Voltage Directive.	邊境拒絕進口 Import rejected at border 產品銷毀 Destruction of the product	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	立陶宛 (Lithuania)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：CX-02</p>	<p>該設備不耐高溫，外殼可能變形，導致帶電部件觸及。用戶可能因觸及帶電部件而觸電。 該產品不符合低電壓指令和歐洲標準 EN 60950-1。 The device is not resistant to high temperatures, its casing may deform, leaving live parts accessible. The user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60950-1.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
34	立陶宛 (Lithuania)	<p>品牌(Brand)：BELLIGHT 品名(Name)：電源延長線 (Extension lead) 型號 (Model)：BL-G03S</p>	<p>用戶可能會接觸到可觸及的帶電部件並受到電擊。 該產品不符合低電壓指令的要求。 The user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
33	匈牙利 (Hungary)	<p>品牌(Brand)：Yoto 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：100LED</p>	<p>電纜固定不當（缺少電纜應力消除裝置），且可觸及電線的絕緣不足。此外，儘管建議戶外使用，但該產品未採用防潮保護措施。水可能會滲入產品，或使用者可能接觸可觸及帶電部件並遭受電擊。 該產品不符合低壓指令和歐洲標準 EN 60598。 The cable is not properly anchored (missing cable strain relief) and the accessible wires have inadequate insulation. Moreover, the product is not protected against moisture although it is recommended for outdoor use. The water could penetrate the product or the user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	匈牙利 (Hungary)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：100LED</p>	<p>電纜缺乏電纜應力消除裝置，因此未正確固定。此外，可觸及電線的絕緣不足。此外，延長線插座的結構允許單極插入插頭，且連接插頭的尺寸不正確。雖然建議在戶外使用，但該產品不具備防潮保護措施。因此，水可能會滲入產品，或者使用者可能接觸到可觸及的帶電部件並遭受電擊。該產品不符合低壓指令和歐洲標準 EN 60598。</p> <p>The cable lacks a cable strain relief and therefore is not properly anchored. Additionally, the accessible wires have inadequate insulation. Moreover, the structure of the cord extension socket allows single-pole insertion of plugs and the dimensions of the connection plug are incorrect. The product is not protected against moisture although it is recommended for outdoor use. Consequently, the water could penetrate the product or the user could touch accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage directive nor with the European standard EN 60598</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
33	匈牙利 (Hungary)	<p>品牌(Brand)：Colorful karaoke sound system 品名(Name)：卡拉ok套裝 (Karaoke set) 型號 (Model)：K12</p>	<p>產品焊料中鉛和鎘的含量超標（測量值分別高達 76%和 0.47%（按重量計）。電纜塑膠材質中鄰苯二甲酸二（2-乙基己基）酯（DEHP）和鄰苯二甲酸二丁酯（DBP）的含量超標（測量值分別高達 0.5%和 0.23%（按重量計）。鉛對環境構成危害。鎘具有生物累積性，對環境構成危害。DEHP 和 DBP 對人類健康和環境構成危害。該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》（RoHS 2.0 指令）的要求。</p> <p>The solders in the product have an excessive concentration of lead and cadmium (measured values up to 76% and 0.47% by weight, respectively). The plastic material of the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 0.5% and 0.23% by weight, respectively). Lead poses a risk to the environment. Cadmium bio-accumulates and poses a risk to the environment. DEHP and DBP pose a risk to human health and the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	匈牙利 (Hungary)	<p>品牌(Brand) : Lampki choinkowe led 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 100B</p>	<p>電纜缺乏電纜應力消除裝置，因此未正確固定。此外，可觸及電線的絕緣不足。此外，延長線插座的結構允許單極插入插頭，且連接插頭的尺寸不正確。雖然建議在戶外使用，但該產品不具備防潮保護措施。因此，水可能會滲入產品，或者使用者可能接觸到可觸及的帶電部件並遭受電擊。該產品不符合低壓指令和歐洲標準 EN 60598 的要求。</p> <p>The cable lacks a cable strain relief and therefore is not properly anchored. Additionally, the accessible wires have inadequate insulation. Moreover, the structure of the cord extension socket allows single-pole insertion of plugs and the dimensions of the connection plug are incorrect. The product is not protected against moisture although it is recommended for outdoor use. Consequently, the water could penetrate the product or the user could touch accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
34	匈牙利 (Hungary)	<p>品牌(Brand) : Rebel POWER 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : ML0950</p>	<p>該產品絕緣不足。用戶可能因接觸帶電部件而觸電。該產品不符合低壓指令和歐洲標準 EN 60335-1。</p> <p>The insulation of the product is inadequate. The user could receive an electric shock from accessible live parts.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335-1.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
34	匈牙利 (Hungary)	<p>品牌(Brand) : INKAX 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : CD-96</p>	<p>該產品絕緣不足。用戶可能因接觸帶電部件而觸電。該產品不符合低壓指令和歐洲標準 EN 60335-1。</p> <p>The insulation of the product is inadequate. The user could receive an electric shock from accessible live parts.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335-1.</p>	<p>從市場撤回 Withdrawal of the product from the market 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025年8月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	匈牙利 (Hungary)	<p>品牌(Brand) : Lampki choinkowe led 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 100W</p>	<p>電纜缺乏電纜應力消除裝置，因此未正確固定。此外，可觸及電線的絕緣不足。此外，延長線插座的結構允許單極插入插頭，且連接插頭的尺寸不正確。雖然建議在戶外使用，但該產品不具備防潮保護措施。因此，水可能會滲入產品，或者使用者可能接觸到可觸及的帶電部件並遭受電擊。該產品不符合低壓指令和歐洲標準 EN 60598 的要求。 The cable lacks a cable strain relief and therefore is not properly anchored. Additionally, the accessible wires have inadequate insulation. Moreover, the structure of the cord extension socket allows single-pole insertion of plugs and the dimensions of the connection plug are incorrect. The product is not protected against moisture although it is recommended for outdoor use. Consequently, the water could penetrate the product or the user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>終端使用者手中召回產品 Recall of the product from end users 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
34	匈牙利 (Hungary)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 100ML</p>	<p>電纜缺乏電纜應力消除裝置，因此未正確固定。此外，可觸及電線的絕緣不足。此外，延長線插座的結構允許單極插入插頭，且連接插頭的尺寸不正確。雖然建議在戶外使用，但該產品不具備防潮保護措施。因此，水可能會滲入產品，或者使用者可能接觸到可觸及的帶電部件並遭受電擊。該產品不符合低壓指令和歐洲標準 EN 60598 的要求。The cable lacks a cable strain relief and therefore is not properly anchored. Additionally, the accessible wires have inadequate insulation. Moreover, the structure of the cord extension socket allows single-pole insertion of plugs and the dimensions of the connection plug are incorrect. The product is not protected against moisture although it is recommended for outdoor use. Consequently, the water could penetrate the product or the user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598</p>	<p>終端使用者手中召回產品 Recall of the product from end users 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025年8月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	匈牙利 (Hungary)	<p>品牌(Brand) : Power Socket HOSPAOP 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : B0DHXVZFT2 F063PD</p>	<p>由於設計不當，該產品可能引起火災。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 Due to incorrect design the product could cause a fire. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
35	匈牙利 (Hungary)	<p>品牌(Brand) : XO 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : XO-WL04 (EU)</p>	<p>該產品絕緣不足，可能導致用戶接觸帶電部件並遭受電擊。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60335-1。 The product is not sufficiently insulated, which could cause the user to have access to live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335-1</p>	<p>終端使用者手中召回產品 Recall of the product from end users 從市場撤回 Withdrawal of the product from the market</p>	
35	匈牙利 (Hungary)	<p>品牌(Brand) : RURI.BW 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : 不詳 (unknown)</p>	<p>電線絕緣不足，可能導致用戶接觸帶電部件並遭受電擊。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60884。 The wires have inadequate insulation, which could cause the user to have access to live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60884.</p>	<p>終端使用者手中召回產品 Recall of the product from end users 從市場撤回 Withdrawal of the product from the market</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
29	匈牙利 (Hungary)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：不詳 (unknown)</p>	<p>該產品設計不當，防觸電保護不足。擺動式插座僅支援單極連接。因此，用戶可能會觸及可接觸帶電部件，從而導致觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The product is improperly designed and not adequately protected against electric shock. The swinging socket enables a one-pole connection. As a result, the user could touch accessible live parts, which may cause an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 從市場撤回 Withdrawal of the product from the market 產品銷毀 Destruction of the product</p>	
30	匈牙利 (Hungary)	<p>品牌(Brand)：Bo Yang 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：025</p>	<p>該產品的電源與電子單元的連接不牢固，且產品絕緣不足，導致帶電部件容易接觸。用戶可能接觸到這些帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The power supply of the product is not securely anchored to the electronic unit, and the product has inadequate insulation, which makes live parts accessible. The user could touch the accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
32	法國 (France)	<p>品牌(Brand)：TIIOI 品名(Name)：充電器 (charger) 型號 (Model)：TOE-19</p>	<p>充電器過熱可能導致部分熔化。這可能導致燒傷和火災。本產品不符合低電壓指令的要求。</p> <p>The charger overheats and may as a consequence partially melt. This can lead to the risk of burns and fire. This product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users</p>	

2025年8月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	法國 (France)	<p>品牌(Brand) : i HOWER 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : H141</p>	<p>該產品絕緣不足。用戶可能因接觸帶電部件而觸電。 該產品不符合低壓指令和歐洲標準 EN 62368-1。 The insulation of the product is inadequate. The user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>終端使用者手中召回產品 Recall of the product from end users</p>	
33	法國 (France)	<p>品牌(Brand) : BRANDT 品名(Name) : 電鍋 (Rice cooker) 型號 (Model) : DRC-7 / SUP515</p>	<p>電器手柄下方蓋子的表面溫度過高。用戶在使用過程中可能會不小心觸碰該表面，導致燙傷。此外，主絕緣的爬電距離不足。這可能導致用戶觸電。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-15。 The surface of the lid underneath the handle of the appliance reaches too high temperatures. The user may inadvertently touch this surface during use, resulting in burns. Additionally, the creepage distances for the main insulation are insufficient. This may lead to the user receiving an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-15.</p>	<p>終端使用者手中召回產品 Recall of the product from end users</p>	
32	斯洛伐克 (Slovakia)	<p>品牌(Brand) : ALIGATOR 品名(Name) : 旅行充電器 (Travel charger) 型號 (Model) : CS102</p>	<p>由於電氣絕緣不足，該產品存在觸電危險。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 The product poses a risk of electric shock because the electrical insulation is insufficient. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users</p>	



2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
32	斯洛伐克 (Slovakia)	品牌(Brand)：不詳 (unknown) 品名(Name)：旅行充電器 (Travel charger) 型號 (Model)：ZK-1015	由於電氣絕緣不足，該產品存在觸電危險。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 The product poses a risk of electric shock because the electrical insulation is insufficient. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	
32	斯洛伐克 (Slovakia)	品牌(Brand)：Salcomp 品名(Name)：電源適配器 (Power adaptor) 型號 (Model)：A2347 EMC 3621	由於電氣絕緣不足，該產品存在觸電危險。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 The product poses a risk of electric shock because the electrical insulation is insufficient. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	
32	斯洛伐克 (Slovakia)	品牌(Brand)：EZRA 品名(Name)：旅行適配器 (Travel adaptor) 型號 (Model)：HC-03	由於電氣絕緣不足，該產品存在觸電危險。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 The product poses a risk of electric shock because the electrical insulation is insufficient. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	斯洛伐克 (Slovakia)	品牌(Brand) : YOURZ 品名(Name) : 適配器 (adaptor) 型號 (Model) : Z7	<p>該產品絕緣性能不佳，導致帶電部件容易接觸。用戶可能接觸到這些易接觸的帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。</p> <p>The product's insulation is inappropriate, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	
33	斯洛伐克 (Slovakia)	品牌(Brand) : LEGAMI 品名(Name) : 旅行適配器 (Travel adaptor) 型號 (Model) : TA0005	<p>由於設計缺陷，需要保護接地的 I 類電器插頭可以插入未連接保護導體的插座。此外，該適配器允許同時拔出兩個插頭，將其中一個插頭插入電源插座後，另一個插頭的觸點部分 (可自由接觸) 會出現電源電壓。因此，用戶可能觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。</p> <p>Due to inadequate design, a plug of a class I appliance requiring protective earthing can be inserted into the socket which does not provide for the connection of the protective conductor. Additionally, the adaptor allows two plugs to be pulled out at the same time, and after inserting one of them into the mains socket, mains voltage appears on the contact part of the other (freely accessible). The user can therefore receive an electric shock</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	
33	斯洛伐克 (Slovakia)	品牌(Brand) : X-start 品名(Name) : 旅行適配器 (Travel adaptor) 型號 (Model) : CDQ-074	<p>該產品接地保護不足，允許單極插頭插入，導致帶電部件觸及。用戶可能接觸到可觸及的帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。</p> <p>The product's earthing protection is inadequate, and it allows single-pole plug insertion, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive and the European standard EN 62368-1.</p>	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	斯洛伐克 (Slovakia)	<p>品牌(Brand) : HAOJUE 品名(Name) : 適配器 (adaptor) 型號 (Model) : LCF-114</p>	<p>該產品絕緣性能不佳，導致帶電部件容易接觸。用戶可能接觸到這些易接觸的帶電部件並遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。 The product's insulation is inappropriate, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users</p>	
33	斯洛伐克 (Slovakia)	<p>品牌(Brand) : Home® 品名(Name) : 適配器 (adaptor) 型號 (Model) : JT-1210</p>	<p>該產品絕緣性能不佳，導致帶電部件容易接觸。用戶可能接觸到這些易接觸的帶電部件並遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。 The product's insulation is inappropriate, leaving live parts accessible. The user could touch the accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 8 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
32	瑞典 (Sweden)	<p>品牌(Brand) : Fresh Kid 品名(Name) : 電子驅蚊器 (Electric mosquito repellent) 型號 (Model) : 3019</p>	<p>該產品短鏈氯化石蠟 (SCCP) 濃度超標 (測量值高達 1.3% (重量百分比))。SCCP 會在環境中持續存在，低濃度時對水生生物具有毒性，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長期通過皮膚接觸這些物質可能致癌。此外，該產品焊料中的鉛濃度超標，電纜塑膠材質中的鄰苯二甲酸二 (2-乙基己基) 酯 (DEHP) 和鄰苯二甲酸二丁酯 (DBP) 濃度超標 (測量值分別高達 75%、2.2% 和 0.2% (重量百分比))。鉛對環境構成風險，而這些鄰苯二甲酸酯對人類健康和環境構成風險。</p> <p>該產品不符合《持久性有機污染物 (POP) 法規》或《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 指令) 的要求。</p> <p>The product has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 1.3% by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. Moreover, the solders of the product have an excessive concentration of lead and the plastic material of the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 75%, 2.2 and 0.2 by weight, respectively). Lead poses a risk to the environment, while these phthalates pose a risk to human health and the environment.</p> <p>The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	瑞典 (Sweden)	<p>品牌(Brand) : Fashion Boutique 品名(Name) : 耳機 (Headphones) 型號 (Model) : P2961</p>	<p>產品中的焊料鉛含量超標 (測量值高達 79.9% (重量百分比))。電纜塑膠材質中鄰苯二甲酸二 (2-乙基己基) 酯 (DEHP) 和短鏈氯化石蠟 (SCCP) 含量超標 (測量值分別高達 1.25% 和 2.8% (重量百分比))。鉛對環境構成威脅。DEHP 對人類健康和環境構成威脅。SCCP 在環境中持久存在, 低濃度下對水生生物有毒, 並在野生動物和人類體內生物累積, 對人類健康和環境構成威脅。 該產品不符合《限制在電子電氣設備中使用某些有害物質指令》(RoHS 2.0) 和《持久性有機污染物 (POP) 法規》的要求。 The solders in the product have an excessive concentration of lead (measured value up to 79.9% by weight). The plastic material of the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and short-chain chlorinated paraffins (SCCPs)(measured value up to 1.25% and 2.8% by weight, respectively). Lead poses a risk to the environment. DEHP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
33	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : LED 頭燈 (LED headlamp) 型號 (Model) : GLT0109</p>	<p>該產品焊料中的鉛含量超標 (測量值: 按重量計高達 2.6%)。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value: up to 2.6% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	



2025年8月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	瑞典 (Sweden)	<p>品牌(Brand) : EUKRATOM 品名(Name) : 電子秤 (Digital scale) 型號 (Model) : 不詳 (unknown)</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 68% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 68% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	
35	瑞典 (Sweden)	<p>品牌(Brand) : Nordic Import 品名(Name) : LED 鏡子 (LED mirror) 型號 (Model) : XW-085</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 62% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 62% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	
35	瑞典 (Sweden)	<p>品牌(Brand) : Nordic Import 品名(Name) : LED 鏡子 (LED mirror) 型號 (Model) : 1000467</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 67% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 67% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	

2025 年 8 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
35	瑞典 (Sweden)	<p>品牌(Brand) : Bered 品名(Name) : 應急無線電通信 (Emergency radio) 型號 (Model) : 07350141160051</p>	<p>該產品焊料中的鉛含量超標 (經測量, 含量高達 70.2% (重量百分比))。鉛對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 70.2% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	
35	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 耳機 (Headphone) 型號 (Model) : P958</p>	<p>產品中的焊料和 USB 線纜中的塑膠含鉛量超標 (經測量, 含量高達 80.6% (重量百分比))。此外, 產品中的焊料中鎘含量超標 (經測量, 含量高達 0.19% (重量百分比))。鉛對環境構成威脅。鎘具有生物累積性, 對環境構成威脅。 該產品不符合《關於限制在電子電氣設備中使用某些有害物質的指令》(RoHS 2.0) 的要求。 The solders in the product and the plastic in the USB cable have an excessive concentration of lead (measured value up to 80.6% by weight respectively). Moreover, a solder in the product has an excessive concentration of cadmium (measured value up to 0.19% by weight). Lead poses a risk to the environment. Cadmium bio- accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
33	義大利 (Italy)	<p>品牌(Brand) : Amazon 品名(Name) : 電暖器 (Electric heater) 型號 (Model) : XH - 1201</p>	<p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-30。 該產品耐壓性不足，如果受到機械應力，帶電部件可能會接觸到。用戶可能會接觸到這些帶電部件並遭受電擊。此外，塑膠外殼的耐熱性也不夠，容易著火。 The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-30. The product is not resistant enough, leaving live parts accessible if subjected to mechanical stress. The user could touch the accessible live parts and receive an electric shock. Additionally, the plastic casing is not sufficiently resistant to heat and can catch fire.</p>	<p>從市場撤回 Withdrawal of the product from the market 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
34	義大利 (Italy)	<p>品牌(Brand) : Raydan home 品名(Name) : 暖風機 (Electric heater) 型號 (Model) : 26051</p>	<p>該產品絕緣不足。用戶可能因接觸帶電部件而觸電。 該產品不符合低壓指令和歐洲標準 EN 62368-1。 The insulation of the product is inadequate. The user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
32	德國 (Germany)	<p>品牌(Brand) : Euphoriajinshi 品名(Name) : 桌面插座 (Table socket) 型號 (Model) : Z300EUW / 300BEU</p>	<p>內置電源插座背面沒有觸摸保護裝置。按規定使用產品時，可能會觸及帶電部件。此外，保護導體與金屬外殼的連接方式不完善。連接方式採用螺釘固定在塗漆金屬上，無法有效防止觸電。因此，用戶可能會觸及帶電部件並遭受電擊。該產品不符合低壓指令和歐洲標準 EN 60335-1 的要求。 There is no touch protection on the back of the built-in power socket. Live parts may be touched when the product is used as intended. Moreover, the way in which the protective conductor is connected to the metallic housing is inadequate. The connection is screwed onto painted metal and does not properly protect against electric shock. The user could consequently touch live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335-1.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 終端使用者手中召回產品 Recall of the product from end users</p>	
33	德國 (Germany)	<p>品牌(Brand) : Wolee 品名(Name) : USB C 充電器 (USB C charger) 型號 (Model) : ZETX100W 01A</p>	<p>電器手柄下方蓋子的表面溫度過高。用戶在使用過程中可能會不小心觸碰該表面，導致燙傷。此外，主絕緣的爬電距離不足。這可能導致用戶觸電。該產品不符合低壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-15。 The clearance and creepage distances between the primary and secondary circuits are inadequate. The user has therefore access to live parts and could receive an electric shock. Moreover, the circuit board does not have the necessary flame retardants and can therefore cause a fire. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>停止銷售 Stop of sales 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 產品銷毀 Destruction of the product 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 8 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
34	德國 (Germany)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：電源延長線 (Extension lead) 型號 (Model)：F35</p>	<p>由於產品設計不正確，該產品可能引起火災。 該產品不符合低壓指令的要求，也不符合歐洲標準 EN 62368-1。 Due to the product's incorrect design, the product could cause a fire. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
32	盧森堡 (Luxembourg)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：吸頂燈 (Ceiling lamp) 型號 (Model)：X6-241-L120cm Black Frame</p>	<p>該燈沒有接地，電線僅受基本絕緣保護，並與金屬部件接觸。如果絕緣損壞，用戶可能會接觸可觸及的帶電部件並遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60598-1 的要求。 The lamp has no earth connection and the wires are protected with basic insulation only and are in contact with the metal parts. In case of insulation damage the user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-1.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 8 月 電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
32	美國 (America)	<p>品牌(Brand) : Altafit 品名(Name) : 智能手錶 (Smartwatches) 型號 (Model) : 不詳 (unknown)</p>	<p>智慧手錶的無線充電板可能會過熱並起火，造成嚴重燒傷和火災危險。 The smartwatch's wireless charging pad can overheat and ignite, posing a risk of serious burn injury and fire hazard.</p>	<p>替換 Replace</p>	
32	美國 (America)	<p>品牌(Brand) : Remington 品名(Name) : 吹風機 (Hair Dryers) 型號 (Model) : D3190DCDN</p>	<p>掌上型吹風機缺乏浸水保護裝置，對消費者而言存在重大產品危害，如果吹風機在插入電源時掉入水中，可能會因觸電或電擊而導致死亡或嚴重受傷。 The handheld hair dryers lack an immersion protection device, which presents a substantial product hazard to consumers, posing the risk of death or serious injury from electrocution or shock if the hair dryers fall into water while plugged in.</p>	<p>退款 Refund</p>	
32	美國 (America)	<p>品牌(Brand) : MiBOXER 品名(Name) : 電子 LED 模組 (Electronic LED modules) 型號 (Model) : E2-WR</p>	<p>LED 模組可能過熱，導致其熔化，造成火災隱患。 The LED module can overheat, causing it to melt, posing a fire hazard.</p>	<p>退款 Refund 替換 Replace</p>	
33	美國 (America)	<p>品牌(Brand) : ESR HaloLock 品名(Name) : 無線充電寶 (Wireless Power Banks) 型號 (Model) : 2G520, 2G505B, 2G512B</p>	<p>召回移動電源中的鋰離子電池可能過熱並起火，對消費者造成火災和燒傷危險。 The lithium-ion battery in the recalled power banks can overheat and ignite, posing fire and burn hazards to consumers.</p>	<p>退款 Refund</p>	

2025 年 8 月 電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
35	美國 (America)	品牌(Brand) : CT-ENERGY 品名(Name) : 鋰電池充電器 (Lithium Coin Battery Chargers) 型號 (Model) : 不詳 (unknown)	<p>召回的電池充電器違反了含有鈕扣電池或硬幣電池的消費品強制性標準，因為該充電器內含鈕扣鋰電池，兒童容易接觸。此外，該充電器附帶的鈕扣電池未採用兒童安全包裝，且包裝上未印有裡斯法案 (Reese's Law) 所要求的警告標識。如果兒童吞食鈕扣電池或硬幣電池，可能導致嚴重傷害、內部化學灼傷甚至死亡。</p> <p>The recalled battery charger violates the mandatory standard for consumer products containing button cell or coin batteries because the charger has lithium coin batteries that can be accessed easily by children. In addition, the coin batteries provided with the battery charger are not in child-resistant packaging, and the packaging does not have the warnings as required by Reese' s Law. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death.</p>	退款 Refund 替換 Replace 修理 Repair	
35	美國 (America)	品牌(Brand) : 不詳 (unknown) 品名(Name) : 電動機 (Electric motors) 型號 (Model) : DOW-136-0-34-XIN, DOW-136-0-26-XIN, DOW-136-0-40-XIN, DOW-136-0-40-XIN-3/4" , and D-RE-PSC-127/20-4P1SP	<p>召回的電動機的安全切斷裝置在使用時可能會造成短路和火災危險。</p> <p>The recalled electric motor's safety cutoff may pose a risk of short circuit and fire hazard while in use.</p>	退款 Refund	