




2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
50	比利時 (Belgium)	<p>品牌(Brand) : HERZBERG 品名(Name) : 電水壺 (Electric kettle) 型號 (Model) : HG-5011</p>	<p>PVC 電纜絕緣層中鉛的遷移量過高 (實測值高達 3600 毫克/千克)。鉛對環境構成風險。此外, 該產品塑膠中鄰苯二甲酸二(2-乙基己基)酯 (DEHP)、鄰苯二甲酸二異丁酯 (DIBP) 和鄰苯二甲酸二丁酯 (DBP) 的含量也過高 (實測值分別高達 49 克/千克、11 克/千克和 16 克/千克)。這些鄰苯二甲酸酯可能損害生殖系統, 從而危害健康。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。</p> <p>The migration of lead from the PVC cable insulation is too high (measured value up to 3,600 mg/kg). Lead poses a risk to the environment. Moreover, the plastic of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), diisobutyl phthalate (DIBP) and dibutyl phthalate (DBP) (measured values up to 49 g/kg, 11 g/kg and 16 g/kg, respectively). These phthalates may harm the health by causing possible damage to the reproductive system.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>產品銷毀 Destruction of the product 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
49	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 洗衣機 (Washing machine) 型號 (Model) : DKS1202</p>	<p>該產品的火線和地線插腳過短, 且靠近插頭邊緣。這可能導致插頭與插座無法牢固連接, 造成接觸不良, 進而導致過熱和火災。此外, 該產品缺少必要的文檔。該產品不符合低電壓指令的要求。</p> <p>The live and earthing pins of the product are too short and close to the periphery of the plug. This may prevent the plug from making a secure connection with the socket. This could lead to poor contact, resulting in overheating and causing fire. Moreover, required documentation is missing.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 邊境拒絕進口 Import rejected at border</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
49	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：吸頂燈 (Ceiling lamp) 型號 (Model)：GX3055-BK40-NTR	變壓器和驅動器的爬電距離和安全距離不足。一旦發生電流浪湧或電氣故障，使用者可能會觸電。 該產品不符合低電壓指令和歐洲標準 EN 60598-1 的要求。 The transformer and drive have insufficient creepage and clearance distances. In the event of a surge in current or electrical fault, the user could receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-1.	邊境拒絕進口 Import rejected at border 產品銷毀 Destruction of the product	
49	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：履行適配器 (Travel adaptor) 型號 (Model)：BK318-4A4C	電源插座的尺寸不符合規格。零線和 ISOD 引腳的尺寸小於允許的公差，這可能導致插頭無法與插座牢固連接。這可能導致接觸不良，進而造成過熱和/或爆炸。 該產品不符合低電壓指令的要求。 The dimensions of the power socket do not comply with the specifications. The neutral and ISOD pins are below the permitted tolerances, which may prevent the plug from making a secure connection with the socket. This could lead to poor contact, resulting in overheating and/or exploding. The product does not meet the requirements of the Low Voltage Directive.	邊境拒絕進口 Import rejected at border	
50	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：電池充電器 (Battery charger) 型號 (Model)：48V2A	保險絲在故障情況下可能無法熔斷，導致插頭過熱和/或爆炸，從而引發火災。電源插頭尺寸不符合規定，且缺少合格的熔斷絲。此外，產品上缺少必要的標記資訊、使用說明和安全資訊。 該產品不符合低電壓指令的要求。 The fuse may fail to operate under fault conditions, leading to the plug overheating and/or exploding, which can cause a fire. The mains plug does not meet the necessary size specifications and is missing a conforming fuse link. Additionally, essential marking information, instructions and safety information are missing on the product. The product does not comply with the requirements of the Low Voltage Directive.	邊境拒絕進口 Import rejected at border	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
50	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：暖風機 (Fan heater) 型號 (Model)：WD-228	<p>電源線電阻過大。長時間使用可能導致電纜過熱並引發火災。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60335-2 的要求。</p> <p>The mains supply cord has excessive resistance. This could lead to the cable overheating and catching on fire if used for extended periods.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335-2.</p>	<p>線上市場刪除了該產品清單</p> <p>Removal of this product listing by the online marketplace</p> <p>邊境拒絕進口</p> <p>Import rejected at border</p>	
50	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：陶瓷爐 (Ceramic cooker) 型號 (Model)：不詳 (unknown)	<p>該產品的插頭未配備符合標準的保險絲。如果產品使用過程中電氣系統發生故障，保險絲可能無法防止火災和爆炸。</p> <p>本產品不符合低電壓指令的要求。</p> <p>The product's plug is not fitted with a conforming fuse. If there is a failure within the electrical system whilst the product is in use, the fuse may fail to prevent fire and explosion.</p> <p>This product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口</p> <p>Import rejected at border</p>	
51	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：LP-60L	<p>該插頭不符合尺寸要求。此外，火線和零線插腳距離插頭外緣過近，且絕緣性能不足。因此，該插頭可能起火和/或爆炸。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The plug does not meet the dimensional requirements. Additionally, the live and neutral pins are too close to the periphery, and the product has insufficient insulation. The plug could therefore catch fire and/or explode.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口</p> <p>Import rejected at border</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : HOPEXY 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : NYB0400A	<p>該插頭尺寸不符合要求，因此無法與插座牢固連接。這可能導致產品在使用過程中產生電弧或火花，從而引發火災。此外，儘管該產品推薦用於戶外，但它並不具備防潮功能。因此，用戶可能接觸到裸露的帶電部件，或者水可能滲入產品內部導致觸電。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The plug does not meet the dimensional requirements and therefore cannot make a secure connection with the socket. This could cause the product to arc or spark during use, leading to a fire. Furthermore, the product is not protected against moisture, despite being recommended for outdoor use. Consequently, the user could touch accessible live parts or water could penetrate the product and cause an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	邊境拒絕進口 Import rejected at border 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace	
52	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand) : Timiyou 品名(Name) : 暖風機 (Fan heater) 型號 (Model) : MST-1212	<p>保險絲可能無法正常工作，導致插頭過熱和/或爆炸，從而引發火災。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The fuse may fail to operate, leading to the plug overheating and/or exploding, which can cause a fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	邊境拒絕進口 Import rejected at border 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace	
51	立陶宛 (Lithuania)	品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 784	<p>該產品絕緣性能不足，使用者可能接觸到裸露的帶電部件，從而導致觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The product has inadequate and insufficient insulation. The user could touch accessible live parts, which may lead to an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	從市場撤回 Withdrawal of the product from the market	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：不詳 (unknown)	<p>該設備不耐高溫，其外殼可能變形，導致內部帶電部件裸露。用戶接觸這些帶電部件可能導致觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60950-1 的要求。</p> <p>The device is not resistant to high temperatures, its casing may deform leaving live parts accessible. The user could touch these live parts, which may lead to an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60950-1.</p>	從市場撤回 Withdrawal of the product from the market	
51	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：電源延長線 (Extension cord) 型號 (Model)：XM-D03	<p>插座未按要求加裝保護蓋。因此，用戶可能因接觸帶電部件而觸電。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The sockets are not protected with covers as required. The user could therefore receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market	
52	西班牙 (Spain)	品牌(Brand)：X-MAS LED 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：KDK-100LED KDK-1120-100LED	<p>電線直徑小於規定尺寸，這可能導致產品過熱並起火。用戶可能接觸到帶電部件，從而遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The diameter of the wire is smaller than required. This could lead the product to overheat and catch fire. The user can access live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	停止銷售 Stop of sales	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	克羅埃西亞 (Croatia)	<p>品牌(Brand) : NEEDIS 品名(Name) : 攪拌機 (Blender) 型號 (Model) : KAHB100CWT</p>	<p>該產品缺少必要的安全聲明和使用說明。這可能導致使用者不當使用該設備，並造成觸電危險。此外，該設備不耐高溫，其外殼可能變形，導致帶電部件暴露。用戶接觸這些帶電部件可能導致觸電。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-14。 The product lacks the required safety statements and instructions for use. This could lead to inappropriate use of the appliance and the user receiving an electric shock. Moreover, the device is not resistant to high temperatures, its casing may deform leaving live parts accessible. The user could touch these live parts, which may lead to an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-14.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 警告消費者風險 Warning consumers of the risks 從市場撤回 Withdrawal of the product from the market</p>	
51	克羅埃西亞 (Croatia)	<p>品牌(Brand) : Elta 品名(Name) : 華夫餅乾機 (Waffle maker) 型號 (Model) : WJ-107</p>	<p>隨著時間的推移，標識標籤會脫落，且缺少必要的安全說明。這可能導致使用者不當使用該設備，並可能造成觸電。此外，該設備不耐高溫，其外殼可能會變形，導致帶電部件裸露。用戶接觸到這些帶電部件可能會導致觸電。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-9。 The marking label detaches with time and the required safety statements are missing. This could lead to inappropriate use of the appliance and the user receiving an electric shock. Moreover, the device is not resistant to high temperatures, its casing may deform leaving live parts accessible. The user could touch these live parts, which may lead to an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-9.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 警告消費者風險 Warning consumers of the risks 從市場撤回 Withdrawal of the product from the market</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
52	克羅埃西亞 (Croatia)	品牌(Brand) : Switch ON 品名(Name) : 油炸鍋 (Deep fryer) 型號 (Model) : 1267663-5221 DF-G0201	<p>油溫可能過高，導致火災和燙傷風險。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-13。</p> <p>The oil may reach too high temperatures. leading to a risk of fire and a risk of burns.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-13.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 從市場撤回 Withdrawal of the product from the market</p>	
49	法國 (France)	品牌(Brand) : HKOENIG 品名(Name) : 電鍋 (Rice cooker) 型號 (Model) : ORIZA4	<p>該電器的電氣絕緣性能不足，可能導致使用者觸電。此外，電源線導體可能過熱，引發火災。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-15。</p> <p>The electrical insulation of the appliance is not sufficiently reliable, which may lead to the user receiving an electric shock. Moreover, the power cable conductors can overheat, leading to fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-15.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 警告消費者風險 Warning consumers of the risks 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
51	法國 (France)	品牌(Brand) : GRTpro 品名(Name) : 吹風機 (hair dryer) 型號 (Model) : BL-F02	<p>通風控制按鈕未牢固固定，可能脫落。幼兒可能將其放入口中導致窒息。此外，按鈕脫落後，帶電部件裸露在外。另開關和設備內部的電線絕緣不足，電線與可觸及部件之間的距離過短。而且，電線焊接處容易老化。因此，用戶可能接觸到帶電部件並觸電。該產品不符合低電壓指令的要求。</p> <p>The button to control ventilation is not properly affixed and may become detached. Small children may put them in the mouth and choke. Furthermore, once the button has detached, live parts are exposed. Additionally, inside the switches and the appliance the electrical wires of the product are not sufficiently insulated. The distance between these wires and accessible parts is insufficient. Moreover, the wires soldering can easily deteriorate. The user can therefore access live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>終端使用者手中召回產品 Recall of the product from end users 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	

2025 年 12 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	法國 (France)	<p>品牌(Brand) : BASUWELL 品名(Name) : 吹風機 (hair dryer) 型號 (Model) : BASU-1601</p>	<p>該產品開關內部的電線絕緣不足。電線與用戶可觸及部件之間的距離不夠。此外，電線焊接處容易老化。因此，用戶可能接觸到帶電部件並觸電。 該產品不符合低電壓指令的要求。 Inside the switches the electrical wires of the product are not sufficiently insulated. The distance between these wires and the parts a user can touch is insufficient. Moreover, the wires soldering can easily deteriorate. The user can therefore access live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
51	法國 (France)	<p>品牌(Brand) : SAWOP 品名(Name) : 吹風機 (hair dryer) 型號 (Model) : SY-BD17</p>	<p>該產品防摔性能不足，存在火災隱患。 該產品不符合低電壓指令的要求。 The product is not sufficiently protected against being dropped, leading to a risk of fire. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
52	法國 (France)	<p>品牌(Brand) : KOONENDA 品名(Name) : 鋰電池 (Lithium battery) 型號 (Model) : CR2032 3V</p>	<p>包裝並非兒童安全包裝，因此鈕扣電池很容易被兒童拿到。兒童可能會將電池放入口中，導致窒息。如果誤食鈕扣電池，也可能對兒童的消化系統造成損害。 本產品不符合通用產品安全法規 (GDPR) 和歐洲標準 EN 60086-4。 The packaging is not childproof and therefore the button batteries are easily accessible to children. A child may put them in the mouth, and choke. The button batteries could also cause damage to the child's gastrointestinal tract if they are ingested. This product does not comply with the General Product Safety Regulation nor with the European standard EN 60086-4.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
52	法國 (France)	<p>品牌(Brand) : TIANQIU 品名(Name) : 鋰電池 (Lithium battery) 型號 (Model) : CR2016 3V</p>	<p>包裝並非兒童安全包裝，因此鈕扣電池很容易被兒童拿到。兒童可能會將電池放入口中，導致窒息。如果誤食鈕扣電池，也可能對兒童的消化系統造成損害。 本產品不符合通用產品安全法規 (GDPR) 和歐洲標準 EN 60086-4。 The packaging is not childproof and therefore the button batteries are easily accessible to children. A child may put them in the mouth, and choke. The button batteries could also cause damage to the child's gastrointestinal tract if they are ingested. This product does not comply with the General Product Safety Regulation nor with the European standard EN 60086-4.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
52	法國 (France)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 鋰電池 (Lithium battery) 型號 (Model) : CR2430 3v</p>	<p>包裝並非兒童安全包裝，因此鈕扣電池很容易被兒童拿到。兒童可能會將電池放入口中，導致窒息。如果誤食鈕扣電池，也可能對兒童的消化系統造成損害。 本產品不符合通用產品安全法規 (GDPR) 和歐洲標準 EN 60086-4。 The packaging is not childproof and therefore the button batteries are easily accessible to children. A child may put them in the mouth, and choke. The button batteries could also cause damage to the child's gastrointestinal tract if they are ingested. This product does not comply with the General Product Safety Regulation nor with the European standard EN 60086-4.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
52	法國 (France)	品牌(Brand) : KOONENDA 品名(Name) : 鋰電池 (Lithium battery) 型號 (Model) : BR2450 CR2450 3V DL2450 KCR5029 LM2450	<p>包裝並非兒童安全包裝，因此鈕扣電池很容易被兒童拿到。兒童可能會將電池放入口中，導致窒息。如果誤食鈕扣電池，也可能對兒童的消化系統造成損害。</p> <p>本產品不符合通用產品安全法規 (GDPR) 和歐洲標準 EN 60086-4。</p> <p>The packaging is not childproof and therefore the button batteries are easily accessible to children. A child may put them in the mouth, and choke. The button batteries could also cause damage to the child's gastrointestinal tract if they are ingested.</p> <p>This product does not comply with the General Product Safety Regulation nor with the European standard EN 60086-4.</p>	<p>線上市場刪除了該產品清單</p> <p>Removal of this product listing by the online marketplace</p> <p>從市場撤回</p> <p>Withdrawal of the product from the market</p> <p>終端使用者手中召回產品</p> <p>Recall of the product from end users</p>	
52	波蘭 (Poland)	品牌(Brand) : GTV 品名(Name) : 燈 (Lamp) 型號 (Model) : XLT-Z3OP20SZ1B-00 XLT-Z3OP20SZ1B-10	<p>保護導體 (PE) 的保護不足。接地橫截面積也不足。因此，用戶可接觸到帶電部件，從而可能遭受電擊。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The protection of the protective conductor (PE) is insufficient. The cross-section area of the earthing is also inadequate. Live parts are therefore accessible to the user, who can receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>從市場撤回</p> <p>Withdrawal of the product from the market</p> <p>終端使用者手中召回產品</p> <p>Recall of the product from end users</p>	
50	芬蘭 (Finland)	品牌(Brand) : Le-On 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : 103594460	<p>該產品的電氣絕緣性能不足，可能導致使用者因接觸帶電部件而觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN62368-1 的要求。</p> <p>The electrical insulation is not sufficient. This can lead to the user receiving an electric shock from accessible live parts.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN62368-1.</p>	<p>終端使用者手中召回產品</p> <p>Recall of the product from end users</p>	


2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	芬蘭 (Finland)	品牌(Brand) : Robitronic 品名(Name) : 電池充電器 (Battery charger) 型號 (Model) : R01015	<p>該產品的絕緣性能以及初級電路和次級電路之間的爬電距離均不足。因此，用戶可能接觸帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60335 的要求。</p> <p>The insulation of the product as well as the creepage distances between the primary and secondary circuits are not sufficient. The user can therefore touch live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335</p>	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	
52	斯洛維尼亞 (Slovenia)	品牌(Brand) : Iskra 品名(Name) : 榨汁機 (juicer) 型號 (Model) : CJ-8005-LI	<p>該產品中的焊料鉛含量過高 (實測值最高達 31% (重量比))。鉛對環境構成威脅。</p> <p>該產品不符合歐盟委員會關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求。</p> <p>The solders in the product have an excessive concentration of lead (measured value up to 31 % by weight). Lead poses a risk to the environment.</p> <p>The product does not comply with the requirements of the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	從市場撤回 Withdrawal of the product from the market	
52	斯洛維尼亞 (Slovenia)	品牌(Brand) : ROSMARINO 品名(Name) : 華夫餅乾機 (Waffle maker) 型號 (Model) : K-902	<p>該產品塑膠中鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 的含量過高 (實測值最高達 1.6% (重量比))。這種鄰苯二甲酸酯可能損害生殖系統，從而危害健康。</p> <p>該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求。</p> <p>The plastic of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured values up to 1.6% by weight). This phthalate may harm the health by causing possible damage to the reproductive system.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 從市場撤回 Withdrawal of the product from the market	



2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
49	瑞典 (Sweden)	<p>品牌(Brand) : Studio 品名(Name) : 耳機 (Headphones) 型號 (Model) : A-6S/SL-14842</p>	<p>該產品中的焊料鉛含量超標 (實測值: 最高達 71.8%重量百分比)。此外, 電纜中的塑膠材料鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 和鄰苯二甲酸二丁酯 (DBP) 含量超標 (實測值分別為 2.36%和 0.11%重量百分比)。鉛對環境構成風險。DEHP 和 DBP 可能損害生殖系統, 危害人體健康, 並對環境造成危害。</p> <p>該產品不符合《關於限制在電氣和電子設備中使用某些有害物質的指令》(RoHS 指令) 的要求。</p> <p>Solders in the product have an excessive concentration of lead (measured value: up to 71.8% by weight). In addition, the plastic material in the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values: 2.36% and 0.11% by weight, respectively). Lead poses a risk to the environment. DEHP and DBP may harm the health by causing possible damage to the reproductive system and to the environment.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
50	瑞典 (Sweden)	<p>品牌(Brand) : ALL RIDE 品名(Name) : LED 格柵裝飾 (LED grill decoration) 型號 (Model) : 不詳 (unknown)</p>	<p>該產品鉛含量超標 (實測值最高達 0.6% (重量比))。鉛對環境構成風險。</p> <p>該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。</p> <p>The product has an excessive concentration of lead (measured value up to 0.6% by weight). Lead poses a risk to the environment</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	瑞典 (Sweden)	<p>品牌(Brand) : Baofeng 品名(Name) : 揚聲器麥克風 (Speaker microphone) 型號 (Model) : 31644</p>	<p>焊料中鉛含量過高 (實測值最高達 64% (重量比))。鉛對環境構成威脅。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders have an excessive concentration of lead (measured value up to 64% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
51	瑞典 (Sweden)	<p>品牌(Brand) : Denver 品名(Name) : 太陽能電池收音機 (Solar cell radio) 型號 (Model) : 31644</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 3% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 3% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
51	瑞典 (Sweden)	<p>品牌(Brand) : Airam 品名(Name) : 自行車燈 (Bicycle light) 型號 (Model) : Snro 8710465</p>	<p>該產品塑膠材料中鉛含量超標 (實測值最高達 0.26% (重量比))。鉛對環境構成威脅。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The plastic material of the product has an excessive concentration of lead (measured value up to 0.26% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	


2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	瑞典 (Sweden)	<p>品牌(Brand) : Prego 品名(Name) : 紅外體溫計 (Infrared thermometer) 型號 (Model) : 86-02040 PM-002C (HG01)</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 76% (重量比))。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 76% by weight). Lead poses a risk to the environment The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
51	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 充電線 (Charging cable) 型號 (Model) : EDA003391503A</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 26% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 26% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	
51	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 充電線 (Charging cable) 型號 (Model) : EDA003391504A</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 34% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 34% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>邊境拒絕進口 Import rejected at border</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈 (Lamp) 型號 (Model)：LDDUK-WRD-BK</p>	<p>保險絲在故障情況下可能無法熔斷，導致插頭過熱，進而引發火災和/或爆炸。此外，產品缺少必要的標識資訊。 該產品不符合低電壓指令的要求。 The fuse may fail to operate under fault conditions, leading to the plug overheating, which can cause a fire and/or explosion. Additionally, essential marking information is missing on the product. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口 Import rejected at border 產品銷毀 Destruction of the product 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
51	瑞典 (Sweden)	<p>品牌(Brand)：Venso EcoSolutions 品名(Name)：燈座適配器 (Lamp holder adaptor) 型號 (Model)：MDM-4249-1 CL</p>	<p>該產品的塑膠材料中鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 的含量過高 (實測值：最高達 20% 重量比)。這種鄰苯二甲酸酯可能對健康造成危害，例如損害生殖系統。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured values: up to 20% by weight). This phthalate may harm the health by causing possible damage to the reproductive system. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
52	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：風扇 (Fan) 型號 (Model)：120D-RGB</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 46% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 46% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
52	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 跳舞墊子 (Dance Mat) 型號 (Model) : 20132303, 03711</p>	<p>該產品中的焊料鉛和鎘含量過高 (實測值分別高達 75.1% 和 0.3% 重量百分比) 。電纜塑膠材料中鄰苯二甲酸二(2-乙基己基)酯 (DEHP)、鄰苯二甲酸二正丁酯 (DBP) 和短鏈氯化石蠟 (SCCPs) 含量過高 (實測值分別高達 1.36%、0.43% 和 4.98% 重量百分比) 。DEHP 和 DBP 對人類健康和環境構成威脅。SCCPs 會在環境中持久存在，低濃度下即可對水生生物產生毒性，並在野生動物和人體內生物累積，對人類健康和環境構成威脅。長期經皮膚接觸可能導致癌症。</p> <p>該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求，也不符合持久性有機污染物 (POP) 法規。</p> <p>The solders in the product have an excessive concentration of lead and cadmium (measured value up to 75.1% and 0.3% by weight, respectively). The plastic material of the cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), di-n-butyl phthalate (DBP) and short chain chlorinated paraffins (SCCPs) (measured value up to 1.36%, 0.43% and 4.98% by weight, respectively). DEHP and DBP pose a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	




2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	德國 (Germany)	<p>品牌(Brand) : Hama 品名(Name) : WiFi 戶外插座 (WiFi outdoor socket) 型號 (Model) : 00176627</p>	<p>隨著時間的推移，該產品外殼可能會出現細微裂紋。由此可能導致水滲入，用戶可能因此觸電。 該產品不符合無線電設備指令 (RED) 的要求。 The product can form hairline cracks in the outer casing along time. As a result, water could enter and the user could receive an electric shock. The product does not comply with the requirements of the Radio Equipment Directive (RED).</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
52	德國 (Germany)	<p>品牌(Brand) : MICHELINO 品名(Name) : 電水壺 (Electric kettle) 型號 (Model) : KL-SG 1835 74353</p>	<p>該產品“黑色塑膠 (插頭)”和“黑色塑膠 (電纜護套)”組件中短鏈氯化石蠟 (SCCPs) 含量過高 (實測值最高達 13%重量比)。SCCPs 會在環境中持久存在，即使低濃度也會對水生生物造成毒害，並在野生動物和人體內生物累積，對人類健康和環境構成威脅。 該產品不符合持久性有機污染物 (POPs) 法規的要求。 The product has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 13% by weight) in the components ‘black plastic (plug)’ and ‘black plastic (cable sheathing)’. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. The product does not comply with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 12 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
52	德國 (Germany)	品牌(Brand) : MICHELINO 品名(Name) : 電水壺 (Electric kettle) 型號 (Model) : 74352	<p>在進口商的同型號水壺中，在“黑色塑膠（插頭）”和“黑色塑膠（電纜護套）”部件中檢測出了短鏈氯化石蠟（SCCPs）。進口商無法排除該產品中 SCCPs 含量也超過限值的可能性。該產品短鏈氯化石蠟（SCCPs）濃度過高（實測值最高達 0.34%（重量比））。SCCPs 會在環境中持久存在，即使低濃度也會對水生生物造成毒害，並且會在野生動物和人體內生物累積，對人類健康和環境構成威脅。長期經皮膚接觸可能導致癌症。</p> <p>該產品不符合持久性有機污染物（POPs）法規的要求。In the importer's similar models of kettle, SCCPs were found in the components 'black plastic (plug)' and 'black plastic (cable sheathing)'. The importer cannot rule out this product also containing a level of SCCPs that exceeds the limit value. The product has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 0.34 % by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer.</p> <p>The product does not comply with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2025 年 12 月電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
49	美國 (America)	<p>品牌(Brand)：INIU 品名(Name)：移動電源 (Power Banks) 型號 (Model)：BI-B41</p>	<p>被召回的移動電源中的鋰離子電池可能會過熱並起火，對消費者構成火災和燒傷危險。 The lithium-ion battery in the recalled power banks can overheat and ignite, posing fire and burn hazards to consumers.</p>	<p>退款 Refund</p>	
50	美國 (America)	<p>品牌(Brand)：VEVOR 品名(Name)：掛燙機 (Garment Steamers) 型號 (Model)：FCL-H09</p>	<p>蒸籠可能會漏水或噴濺熱水，對使用者和旁觀者造成嚴重燙傷的風險。水箱蓋在使用過程中也可能發生洩漏或脫落，使使用者接觸到熱水。 The steamers can leak or spit hot water, posing a risk of serious burn injury to users and bystanders. The water tank cap can also leak or detach during use, exposing users to hot water.</p>	<p>退款 Refund</p>	
51	美國 (America)	<p>品牌(Brand)：ANNQUAN 品名(Name)：電源板 (Power Strips) 型號 (Model)：EX-D112-05, EX-D106-25</p>	<p>這些電源插座沒有額外的過流保護裝置，如果超載使用，可能會引發火災。由此引發的火災會導致吸入濃煙和燒傷，造成嚴重人身傷害甚至死亡。 The power strips do not contain supplementary overcurrent protection, which creates a risk of fire if the power strips are overloaded. The resulting fire can cause serious injury or death from smoke inhalation and burns.</p>	<p>退款 Refund</p>	

2025 年 12 月電子電氣產品召回案例 (亞太地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
49	澳洲 (Australia)	<p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：USB 可充電茶燭 (USB Rechargeable LED Tealights)</p> <p>型號 (Model)：XX8114160</p>	<p>該產品不符合含鈕扣/硬幣電池產品的強制性標準。</p> <p>該產品在銷售前未經測試。</p> <p>該產品缺少以下警告資訊： 鈕扣/硬幣電池對兒童的危害； 當懷疑有人吞食或將鈕扣/硬幣電池放入體內時應採取的措施。</p> <p>The product doesn't comply with the mandatory standards for products containing button/coin batteries.</p> <p>The product wasn't tested prior to sale.</p> <p>The product is missing warning information about the dangers of button/coin batteries to children</p> <p>what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body.</p>	<p>請立即停止使用本產品，並將其放在兒童接觸不到的地方。</p> <p>請勿取出產品中的電池。</p> <p>請將產品退回購買地點，我們將全額退款。</p> <p>Stop using the products immediately and keep them out of reach of children.</p> <p>Do not remove the batteries from the product.</p> <p>Return the products to the place of purchase for a full refund.</p>	
51	澳洲 (Australia)	<p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：45cm 高速基座風扇 (45cm high velocity pedestal fan)</p> <p>型號 (Model)：不詳 (unknown)</p>	<p>消費者接觸帶電部件有觸電致重傷或死亡的風險。</p> <p>Risk of serious injury or death from electric shock or electrocution if consumers touch live parts.</p>	<p>立即停止使用風扇並斷開電源。</p> <p>前往任何一家 BIG W 門店 (Contempo 品牌) 或 Woolworths 超市門店 (Adesso 品牌) 即可獲得全額退款。</p> <p>如果您無法退貨或已將產品出售或贈送，請聯繫 BIG W 或 Woolworths 超市。</p> <p>Stop using the fan immediately and disconnect it from power.</p> <p>Return to any BIG W store (Contempo Brand) or Woolworth Supermarkets store (Adesso Brand) for a full refund</p> <p>Contact Big W or Woolworth Supermarkets if you are unable to return the product or have sold or gifted it</p>	

2025年12月電子電氣產品召回案例 (亞太地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
51	澳洲 (Australia)	<p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：電視遙控器 (TV remote control)</p> <p>型號 (Model)：不詳 (unknown)</p>	<p>兒童吞食或將鈕扣電池放入體內可能導致窒息、嚴重內傷甚至死亡。</p> <p>嚴重傷害可能在短短兩小時內發生，甚至危及生命。在澳洲，已有兒童因吞食鈕扣電池而遭受嚴重傷害或死亡。</p> <p>Children are at risk of choking, severe internal burn injuries or death if they swallow or place button/coin batteries inside their bodies.</p> <p>Serious injury can occur in as little as 2 hours and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.</p>	<p>請立即停止使用遙控器，並將其放在兒童接觸不到的地方。</p> <p>請通過 Kogan.com.au 聯繫 Auntie Mary Warehouse，並提供您的訂單號以獲得全額退款。</p> <p>請根據當地法規處理遙控器。</p> <p>Stop using the remote immediately and keep out of reach of children.</p> <p>Contact Auntie Mary Warehouse via Kogan.com.au and provide your order number to receive a full refund.</p> <p>Dispose of the remote according to local regulations.</p>	
50	韓國(Korea)	<p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：電池 (Battery)</p> <p>型號 (Model)：JT-EBB10-42, 36V8.7AH</p>	<p>有起火和爆炸的風險。</p> <p>Risk of ignition and explosion</p>	<p>請聯繫或前往客服中心辦理維修、換貨、退款等事宜。</p> <p>已購買該產品的消費者應立即停止使用。</p> <p>Contact or visit the contact desk to receive repairs, exchanges, refunds, etc. Consumers who have the product should stop using it immediately.</p>	
50	韓國(Korea)	<p>品牌(Brand)：지엠지모터스</p> <p>品名(Name)：電靠墊 (Electric cushion)</p> <p>型號 (Model)：DUHC-2406</p>	<p>正常使用過程中，溫度過高可能導致火災風險。</p> <p>存在提供錯誤資訊的風險。</p> <p>There is a risk of fire due to excessive temperature rise during normal use. There is a risk of providing incorrect information.</p>	<p>請聯繫或前往客服中心辦理維修、換貨、退款等事宜。</p> <p>已購買該產品的消費者應立即停止使用。</p> <p>Contact or visit the contact desk to receive repairs, exchanges, refunds, etc. Consumers who have the product should stop using it immediately.</p>	