



2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|--|--|---|--|---|
| 1 | 德國 (Germany) | 品牌(Brand) : Type-c 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : KeKe-PD003 | <p>初級和次級電路之間的爬電距離和電氣間隙不夠。用戶可能會接觸帶電部件並遭受電擊。而且，外殼的材料是易燃的，可能會導致火災。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 62368。The creepage and clearance distance between the primary and the secondary circuits are not sufficient. The user can be exposed to live parts and receive an electric shock. Moreover, the material of the casing is flammable, which may lead to a fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368.</p> | 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks |  |
| 2 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | 品牌(Brand) : Blackstar 品名(Name) : 電吉他音箱 (Electric guitar amplifier) 型號 (Model) : Debut 100R - 112 Black - 273101-VB Debut 100R - 112 Cream - 273101-VA Debut 100R - 212 Black - 273102-VB Debut 100R - 212 Cream - 273102-VA | <p>由於櫃體木質部件之間間隙不夠大，一些電子元件可能會被觸及或部分暴露。因此，用戶可能會接觸帶電部件並遭受電擊。</p> <p>該產品不符合低電壓指令的要求，也不符合 EN 62368-1 標準</p> <p>Due to an inadequate larger gap between wooden parts of the cabinet, some electronic components may become accessible or partially exposed. As a result, a user could come into contact with live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with standard EN 62368-1</p> | 整改 Modification programme |  |
| 2 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | 品牌(Brand) : GIZMIFY 品名(Name) : LED 燈串 (LED string lights) 型號 (Model) : AWD-001 | <p>插頭尺寸過大，長時間插拔插頭可能會損壞插座，或者使用者可能將不同電器的插頭插入插座，可能無法正確連接，導致插頭過熱起火，引發火災。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 61347-1、EN 61347-2-13 和 EN 60598-2-20，也不符合標準 EN 60598-1</p> <p>The plug is oversized, and over time inserting and removing the plug could damage the socket, or the user may insert the plug of a different appliance into the socket, which may not connect properly, causing the plug to overheat and ignite, causing a fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 61347-1, EN 61347-2-13, and EN 60598-2-20, nor with standard EN 60598-1</p> | 邊境拒絕進口 Import rejected at border |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|--|---|---|--|--|
| 2 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：旅行適配器 (Travel adaptor) 型號 (Model)：EP-TA845</p> | <p>該產品絕緣不充分，使用戶面臨觸電危險。此外，如果絕緣層破裂，內部元件可能會過熱並點燃，從而引起火災。 該產品不符合低電壓指令的要求。 The product is inadequately insulated, exposing the user to a risk of electric shock. Moreover, if the insulation were to break down, internal components could overheat and ignite, causing a fire. The product does not comply with the requirements of the Low Voltage Directive.</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：電動跳舞毯 (Electrical dance mat) 型號 (Model)：051500CN</p> | <p>電線的塑膠材料含有過量濃度的鄰苯二甲酸二 (2-乙基己) 酯 (DEHP)、鄰苯二甲酸二丁酯 (DBP) 和短鏈氯化石蠟 (SCCP) (測量值：按重量計分別高達 0.12%、0.84% 和 2.6%)。產品中的焊料鉛濃度過高 (測量值：按重量計高達 68.8%)。DEHP 和 DBP 對人類健康和環境構成風險。鉛對環境構成風險。鉛對環境構成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的委員會指令 (RoHS 指令) 的要求，也不符合持久性有機污染物 (POP) 法規的要求。The plastic material of the cord has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP) and short-chain chlorinated paraffins (SCCPs) (measured values: up to 0.12%, 0.84% and 2.6% by weight, respectively). The solders in the product have an excessive concentration of lead (measured value: up to 68.8 % by weight). DEHP and DBP pose a risk to human health and the environment. Lead poses a risk to the environment. Lead poses a risk to the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p> | <p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|--|---|--|---|---|
| 3 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | 品牌(Brand) : Waizhiua 品名(Name) : 膠槍 (Glue gun) 型號 (Model) : 不詳 (unknown) | <p>插頭插腳距離插頭周邊太近。從插座上插拔插頭時，使用者可能會因可觸及的帶電部件而受到電擊。此外，接地針有護套，因此無法與插座中的大地正確接觸。該插頭是“三葉草式”插頭，由於接地不充分，無法充分防止火災風險。 該產品不符合低電壓指令的要求。</p> <p>The plug pins are too close to the periphery of the plug. Users can receive an electric shock from accessible live parts when plugging or unplugging the plug from the socket. Moreover, the earth pin is sheathed, so it does not contact the earth in the socket properly. The plug is a 'clover-style' plug, which provides insufficient protection against the risk of fire as it is inadequately earthed.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p> | 邊境拒絕進口 Import rejected at border |  |
| 3 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | 品牌(Brand) : 不詳 (unknown) 品 名(Name) : 萬聖節裝扮 (Halloween decoration) 型號 (Model) : 491660150 | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 82%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have an excessive concentration of lead (measured value up to 82% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | 從市場撤回 Withdrawal of the product from the market |  |
| 4 | 北愛爾蘭 (United Kingdom in respect of Northern Ireland) | 品牌(Brand) : ELPINE 品名(Name) : 電暖氣 (Electric heater) 型號 (Model) : 31492N | <p>只需用最小的力就可以接觸到加熱元件，從而導致電擊。此外，由於插頭面的尺寸，使用者在將插頭拔出或插入插座時可能會受到電擊。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 60335-2。</p> <p>The heating element can be accessed with minimal force, leading to electric shocks. Moreover, due to the size of the plug face, the user can receive an electric shock, while unplugging, or plugging in, the plug into the socket.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard 60335-2.</p> | 終端使用者手中召回產品 Recall of the product from end users |  |

2025年1月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-----------------|---|---|--|---|
| 1 | 立陶宛 (Lithuania) | 品牌(Brand) : MOON 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : ML42B | 該產品絕緣性能不足。結果，用戶可能會受到電擊。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598。 The product has inadequate insulation. As a result, the user may receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598. | 從市場撤回 Withdrawal of the product from the market |  |
| 3 | 立陶宛 (Lithuania) | 品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 9973 | 該產品絕緣性能不足。用戶可能會觸摸可觸及的帶電部件並受到電擊。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598。 The product has inadequate insulation. The user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598. | 從市場撤回 Withdrawal of the product from the market |  |
| 3 | 立陶宛 (Lithuania) | 品牌(Brand) : IEK 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : Y02K | 該產品絕緣性能不足。用戶可能會觸摸可觸及的帶電部件並受到電擊。 該產品不符合低電壓指令的要求。 The product has inadequate insulation. The user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive. | 從市場撤回 Withdrawal of the product from the market |  |
| 4 | 立陶宛 (Lithuania) | 品牌(Brand) : MOON 品名 (Name) : 燈鏈 (Lighting chain) 型號 (Model) : ML41Z | 電氣絕緣不夠。結果，用戶可能會受到電擊。該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598。 The electrical insulation is inadequate. As a result, the user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598. | 從市場撤回 Withdrawal of the product from the market |  |

2025年1月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-----------------|---|---|---|---|
| 4 | 立陶宛 (Lithuania) | <p>品牌(Brand) : NALK&REY 品名(Name) : 吹風機 (Hair dryer) 型號 (Model) : NRHD2200-23</p> | <p>產品電機葉片安裝錯誤可能會產生火花和煙霧，從而導致燒傷和火災。 該產品不符合低電壓指令的要求 Faulty attachment of the product's motor blade may cause sparks and smoke, which could lead to burns and fire. The product does not comply with the requirements of the Low Voltage Directive</p> | <p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p> |  |
| 3 | 西班牙 (Spain) | <p>品牌(Brand) : Luz Europa 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 20002 YY-50C-LO-WH</p> | <p>產品線徑不足，容易發熱，有灼傷使用者的危險。此外，產品上缺乏警告和說明可能會導致用戶在使用適配器時接觸到帶電部件，而沒有意識到處理該產品所帶來的風險。這增加了用戶觸電的風險。 該產品不符合低電壓指令或歐洲標準 EN 60598 的要求。 The cable of the product has an insufficient diameter, hence heating up easily and creating a risk of burns for the user. Moreover, a lack of warnings and instructions on the product, can lead a user to access live parts when using the adaptor being unaware of the risks resulting from handling the product. This increases the risk of the user receiving an electric shock. The product does not comply with the requirements of the Low Voltage Directive or those of European standard EN 60598.</p> | <p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 從市場撤回 Withdrawal of the product from the market</p> |  |
| 4 | 西班牙 (Spain) | <p>品牌(Brand) : Travel Blue 品名(Name) : 適配器 (Adaptor) 型號 (Model) : 901/14802</p> | <p>防護等級為 I 的電器的插頭可以插入防護等級為 II 的電器的插座中。可以僅將插頭的一根插腳部分插入適配器中。如果只有一個插腳插入插座，使用者可能會觸摸插頭的另一插腳並受到電擊。 該產品不符合一般產品安全法規。 The plug of a protection class-I appliance can be inserted into the socket intended for appliances of protection class-II. It is possible to partially insert just one pin of the plug into the adaptor. If only one of the pins is inserted into a socket, the user could touch the other pin of the plug and receive an electric shock. The product does not comply with the General Product Safety Regulation.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-----------------|---|---|---|---|
| 4 | 西班牙 (Spain) | <p>品牌(Brand) : AIGOSTAR 品名 (Name) : 適配器 (Adaptor) 型號 (Model) : NEO3723061208X001DXUU9RXX-GK3012</p> | <p>可以使用普通螺絲刀打開適配器，而不會使其完全無法使用。使用者可能會錯誤地操作它，觸摸可觸及的帶電部件並遭受電擊。該產品不符合低電壓指令的要求。The adaptor can be opened using an ordinary screwdriver without leaving it totally unusable. The user could handle it incorrectly, touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 3 | 克羅埃西亞 (Croatia) | <p>品牌(Brand) : Iskra 品名(Name) : 吹風機 (Hair dryer) 型號 (Model) : RH-1558-1BL</p> | <p>由於熱塑性材料的耐熱性不足，該材料可能會劣化。用戶可能會觸及帶電部件，從而導致觸電風險。該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335。 Due to the inadequate resistance of the thermoplastic material to heat, the material can deteriorate. A user can access live parts, leading to a risk of electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60335.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 3 | 波蘭 (Pland) | <p>品牌(Brand) : REBEL 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : ML0950</p> | <p>焊料中鉛濃度過高 (測量值高達 47.7%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders have an excessive concentration of lead (measured value up to 47.7%). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks</p> |  |
| 1 | 波蘭(Poland) | <p>品牌(Brand) : IRNA 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : P-32</p> | <p>防護等級為 I 的電器的插頭可以插入延長線的插座中，適用於防護等級為 II 的電器。將 I 類設備連接到延長線的用戶可能會受到電擊。該產品不符合低電壓指令的要求，也不符合 IEC 60884-1 和 IEC 60884-2-7 標準。 The plug of a protection class-I appliance can be inserted into the socket of the extension lead, intended for appliances of protection class-II. A user who connects a class-I device to the extension lead may receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the standards IEC 60884-1 and IEC 60884-2-7.</p> | <p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks</p> |  |




2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|--------------|--|---|---|---|
| 3 | 芬蘭 (Finland) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：A2347 EMC 3621 (C4H0012SSB4L9JHZR)</p> | <p>危險帶電初級部件和可觸及的 USB 輸出連接器之間的絕緣不充分。用戶可能會因可觸及的帶電部件而遭受電擊。該產品不符合低電壓指令和相關歐洲標準 EN 62368-1 的要求。The insulation between the hazardous live primary parts and the accessible USB output connector is not adequate. A user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 62368-1.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |
| 3 | 芬蘭 (Finland) | <p>品牌(Brand)：ARMYTEK 品名(Name)：LED 手電筒 (LED flashlight) 型號 (Model)：VIKING PRO</p> | <p>一、二次電路之間的電氣絕緣和爬電距離不夠 (測量值：0.3mm)。用戶可能會因電池充電器的可觸及帶電部件而遭受電擊。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 61558。 The electrical insulation and the creepage distance between the primary and secondary circuits are not sufficient (measured value: 0.3 mm). A user could receive an electric shock from accessible live parts from the battery charger. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 61558.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |
| 3 | 芬蘭 (Finland) | <p>品牌(Brand)：PD 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：SDC-20W (SKU 214828)</p> | <p>危險帶電初級部件和可觸及的 USB 輸出連接器之間的絕緣不充分。用戶可能會因可觸及的帶電部件而遭受電擊。 該產品不符合低電壓指令和相關歐洲標準 EN 62368-1 的要求。 The insulation between the hazardous live primary parts and the accessible USB output connector is not adequate. A user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 62368-1.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |
| 3 | 芬蘭 (Finland) | <p>品牌(Brand)：Liitokala 品名(Name)：電池充電器 (Battery charger) 型號 (Model)：Lii-42-2000</p> | <p>危險帶電初級部件和可觸及的 USB 輸出連接器之間的絕緣不充分。用戶可能會因可觸及的帶電部件而遭受電擊。 該產品不符合低電壓指令和相關歐洲標準 EN 60335 的要求。 The insulation between the hazardous live primary parts and the accessible USB output connector is not adequate. A user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |




2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-----------------|--|--|--|---|
| 3 | 芬蘭 (Finland) | 品牌(Brand) : XO 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : XO-L109(EU) | 危險帶電初級部件和可觸及的 USB 輸出連接器之間的絕緣不充分。用戶可能會因可觸及的帶電部件而遭受電擊。該產品不符合低電壓指令和相關歐洲標準 EN 62368-1 的要求。The insulation between the hazardous live primary parts and the accessible USB output connector is not adequate. A user could receive an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 62368-1. | 終端使用者手中召回產品 Recall of the product from end users |  |
| 1 | 馬爾他 (Malta) | 品牌(Brand) : Lampada 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : 23101-2 | 該產品絕緣性能不足。用戶可能會觸摸可觸及的帶電部件並受到電擊。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598-2-20。 The product has inadequate insulation. The user could touch accessible live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-2-20. | 從市場撤回 Withdrawal of the product from the market |  |
| 1 | 馬爾他 (Malta) | 品牌(Brand) : 不詳 (unknown) 品名(Name) : LED 燈 (LED light) 型號 (Model) : w-20-5 | 由於產品的機械強度不足，用戶可能會觸及帶電部件而觸電。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598-2-20。 Due to insufficient mechanical strength of the product, the user may access live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-2-20. | 從市場撤回 Withdrawal of the product from the market |  |
| 2 | 斯洛伐克 (Slovakia) | 品牌(Brand) : 不詳 (unknown) 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : AJ-1004 | 由於機械強度不足、導體標稱橫截面不足以及防潮保護不足，用戶可能會接觸到帶電部件而遭受電擊。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598-1 和 EN 60598-2-20。 Due to insufficient mechanical strength, inadequate nominal cross-section of the conductors, and inadequate moisture protection, the user may have access to live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60598-1 and EN 60598-2-20. | 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-----------------|---|---|---|---|
| 2 | 斯洛伐克 (Slovakia) | 品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：RPBL-96L | <p>由於機械強度不足、導體標稱橫截面不足以及防潮保護不足，用戶可能會接觸到帶電部件並遭受電擊。該產品不符合低電壓指令的要求，也不符合相關歐洲標準 EN 60598-1 和 EN 60598-2-20。Due to insufficient mechanical strength, an insufficient nominal cross-section of the conductors, and inadequate moisture protection, the user may have access to live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the relevant European standards EN 60598-1 and EN 60598-2-20.</p> | 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks |  |
| 4 | 斯洛伐克 (Slovakia) | 品牌(Brand)：KONDELA 品名(Name)：聖誕樹 (Christmas tree) 型號 (Model)：WHITE BIRCH 90cm A191106 | <p>該產品設計不當，機械強度不夠，叉子與第一個插座之間的電纜長度不夠，防觸電保護不充分。因此，用戶可能會觸摸帶電部件並受到電擊。該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60598-1 和 EN 60598-2-20。The product is improperly designed, with insufficient mechanical strength, an insufficient length of the cable between the fork and the first socket, and not adequately protected against electric shock. The user could consequently touch live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60598-1 and EN 60598-2-20.</p> | 從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks |  |
| 1 | 瑞典 (Sweden) | 品牌(Brand)：Puluz 品名(Name)：LED 環形燈 (LED ring lamp) 型號 (Model)：不詳 (unknown) | <p>該產品焊料中鉛含量過高 (測量值按重量計高達 52.4%)。鉛對環境造成風險 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令)。The product contains excessive concentrations of lead in solders (measured value up to 52.4 % by weight). Lead poses a risk to the environment The product does not comply with the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | 從市場撤回 Withdrawal of the product from the market |  |


2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|---|
| 1 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：3LED 手持放大鏡 (With 3LED Hand-held magnifier) 型號 (Model)：6902AB</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 66%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have an excessive concentration of lead (measured value up to 66 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 1 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：信號燈 (Stoplight) 型號 (Model)：不詳 (unknown)</p> | <p>產品中的焊料鉛濃度過高 (測量值按重量計高達 82%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have an excessive concentration of lead (measured value up to 82 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 1 | 瑞典 (Sweden) | <p>品牌(Brand)：Coolstuff 品名(Name)：燈 (Lamp) 型號 (Model)：20619</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 55%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have an excessive concentration of lead (measured value up to 55% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |


2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|---|---|
| 2 | 瑞典 (Sweden) | 品牌(Brand) : Multifunction Outdoor 品名(Name) : 緊急廣播 (Emergency radio) 型號 (Model) : 366 | <p>該產品焊料中鉛濃度過高 (測量值按重量計高達 73.8%)。電線的塑膠材料含有過量濃度的鄰苯二甲酸二(2-乙基己)酯 (DEHP)、鄰苯二甲酸二丁酯 (DBP) 和短鏈氯化石蠟 (SCCP) (按重量計測量值分別高達 0.8%、1.65% 和 2.1%)。鉛對環境構成風險。DEHP 和 DBP 對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令)、持久性有機污染物 (POP) 法規或 REACH 法規的要求。The product has an excessive concentration of lead in solders (measured value up to 73.8 % by weight). The plastic material of the cord has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP) and short-chain chlorinated paraffins (SCCPs) (measured values up to 0.8%, 1,65% and 2.1 % by weight, respectively). Lead poses a risk to the environment. DEHP and DBP pose a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive) nor with the Persistent Organic Pollutants (POP) Regulation nor with the REACH Regulation.</p> | 從市場撤回 Withdrawal of the product from the market |  |


2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|--|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：遙控拷貝機 (Remote control duplicator) 型號 (Model)：YET2130</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 55%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 55% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：攝像頭 (Camera) 型號 (Model)：不詳 (unknown)</p> | <p>焊料中鉛濃度過高（按重量計測量值高達 46%）。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 46% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：TEMPO DI SALDI 品名(Name)：電源延長線 (Extension cord) 型號 (Model)：30m</p> | <p>該產品的插頭上沒有接地插座，因此無法保護使用者免受連接中斷的影響，並可能遭受電擊。 該產品不符合低電壓指令的要求。 The product does not have an earthing socket on the plug, the user is therefore not protected from disrupted connection and may receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |

2025 年 1 月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|---|---|---|
| 2 | 瑞典 (Sweden) | 品牌(Brand)：不詳 (unknown) 品 名(Name)：幹鞋器 (Shoe Dryer) 型號 (Model)：FC-0526C | <p>焊料中的鉛濃度過高（測量值按重量計高達 61%）。電纜塑膠中的 DEHP 濃度過高（測量值按重量計高達 0.29%）。塑膠電纜還含有過量濃度的短鏈氯化石蠟 (SCCP)（測量值按重量計高達 0.8%）。鉛對環境構成風險。DEHP 對人類健康和環境構成風險。SCCP 在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合持久性有機污染物 (POP) 法規、關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 以及 REACH 法規。The solders have an excessive concentration of lead (measured value up to 61 % by weight). The plastic of the cable has an excessive concentration of DEHP (measured value up to 0.29 % by weight). The plastic cable has also excessive concentrations of short-chain chlorinated paraffins (SCCPs) (measured value up to 0.8 % by weight). Lead poses a risk to the environment. DEHP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive), nor with the REACH Regulation.</p> | 從市場撤回 Withdrawal of the product from the market |  |

2025 年 1 月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|---|---|
| 2 | 瑞典 (Sweden) | 品牌(Brand)：不詳 (unknown) 品名(Name)：HDMI 電源線 (HDMI cable) 型號 (Model)：FC-0526C | <p>電纜的塑膠材料中鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 濃度過高 (測量值按重量計高達 0.37%)。該塑膠還含有超濃度的短鏈氯化石蠟 (SCCP) (按重量計測量值高達 1.15%) DEHP，對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令)、持久性有機污染物 (POP) 法規以及 REACH 法規的要求。The plastic material of the cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0.37 % by weight). The plastic also has excessive concentrations of short-chain chlorinated paraffins (SCCPs) (measured value up to 1.15 % by weight) DEHP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation, nor with the REACH Regulation.</p> | 從市場撤回 Withdrawal of the product from the market |  |

2025 年 1 月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：Padwer 品名 (Name)：無線充電滑鼠墊 (Wireless charging mouse mat) 型號 (Model)：V0103216</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 68%)。塑膠中的 DBP 和 DEHP 濃度超標 (按重量計測量值分別高達 2.2 % 和 2.3 %)。塑膠電纜中的短鏈氯化石蠟 (SCCP) 濃度也超標 (按重量計測量值高達 2.4 %)。鉛對環境構成風險。DEHP 和 DBP 對人類健康和環境構成風險，而 SCCPs 在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合持久性有機污染物 (POP) 法規、關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求，也不符合 REACH 法規。The solders in the product have an excessive concentration of lead (measured value up to 68 % by weight). The plastic has excessive concentrations of DBP and DEHP (measured value up to 2.2 and 2,3 % by weight, respectively) The plastic cable has also excessive concentrations of short-chain chlorinated paraffins (SCCPs) (measured value up to 2,4 % by weight). Lead poses a risk to the environment. DEHP and DBP pose a risk to human health and the environment, while SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the REACH Regulation.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：加熱襪子 (Heated socks) 型號 (Model)：HS-YLZHL16S1-11D</p> | <p>焊料中的鉛濃度過高 (測量值按重量計高達 27%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of lead (measured value up to 27% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : Innovagoods 品名 (Name) : 無線揚聲器 (Wireless speaker) 型號 (Model) : Sunker</p> | <p>焊料中鎘濃度過高 (測量值按重量計高達 0.6%)。鎘會生物累積並對環境造成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of cadmium (measured value up to 0.6 % by weight). Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : Innovagoods 品名(Name) : 帶無線充電器的手機支架 (Mobile phone holder with wireless charger) 型號 (Model) : V0103067</p> | <p>焊料中的鉛濃度過高 (測量值高達 0.27% (重量))。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of lead (measured value up to 0.27 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : microhoo 品名(Name) : 冷風機 (Air cooler) 型號 (Model) : Snowman lite</p> | <p>焊料中的鉛濃度過高 (測量值按重量計高達 36%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of lead (measured value up to 36% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：無線充 (Wireless charger) 型號 (Model)：不詳 (unknown)</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 48%）。塑膠電纜的 DBP 和 DEHP 濃度過高（按重量計測量值分別高達 0.1% 和 2.4%）。塑膠電纜還含有過量濃度的短鏈氯化石蠟 (SCCP)（測量值按重量計高達 1.25%）。鉛對環境造成風險 DEHP 和 DBP 對人類健康和環境造成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合持久性有機污染物 (POP) 法規，也不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）。The solders have an excessive concentration of lead (measured value up to 48 % by weight). The plastic cable has excessive concentrations of DBP and DEHP (measured value up to 0.1 and 2.4 % by weight, respectively). The plastic cable has also excessive concentrations of short-chain chlorinated paraffins (SCCPs) (measured value up to 1.25 % by weight). Lead poses a risk to the environment DEHP and DBP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：Handheld KTV 品名 (Name)：麥克風 (Microphone) 型號 (Model)：WS-858</p> | <p>產品中的焊料鉛和鎘濃度過高（按重量計測量值分別高達 83.4% 和 0.65%）。鉛對環境構成風險。鎘會生物累積並對環境造成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。The solders in the product have excessive concentrations of lead and cadmium (measured values up to 83.4 % and 0.65% by weight, respectively). Lead poses a risk to the environment. Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|---|---|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：加熱鞋墊 (Heating insole) 型號 (Model)：HS-YLZHL06M2-11D</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 49%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 49% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：美髮棒 (Hot Air Styler) 型號 (Model)：不詳 (unknown)</p> | <p>焊料中鉛濃度過高（按重量計測量值高達 46.3%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 46.3% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：適配器 (Adaptor) 型號 (Model)：不詳 (unknown)</p> | <p>產品中的焊料鉛濃度超標（實測值高達 68%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 Solders in the product have an excessive concentration of lead (measured value up to 68%). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|---|--|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : Telebrands 品名 (Name) : 寵物之家修剪器 (Pet nail trimmer) 型號 (Model) : Telebrands</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 74.77%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have an excessive concentration of lead (measured value up to 74.77% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 電子秤 (Digital scale) 型號 (Model) : GL-03/KEB-DHGL05-11D</p> | <p>焊料中的鉛濃度過高 (測量值按重量計高達 48%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of lead (measured value up to 48% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 自動風扇 (Auto Fan) 型號 (Model) : 55956</p> | <p>焊料中的鉛濃度過高 (測量值按重量計高達 74%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders have an excessive concentration of lead (measured value up to 74 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|--|--|---|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：智能手錶充電器 (Smartwatch charger) 型號 (Model)：PB-0S38-12D</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 34%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 34% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：KONG 品名(Name)：鐳射筆 (Laser pointer) 型號 (Model)：CL4E Laser Pointer EU</p> | <p>產品中的焊料鉛濃度過高（按重量計測量值高達 71.6%）。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders in the product have an excessive concentration of lead (measured value up to 71.6 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：Brommavik hotel 品名(Name)：移動電源 (Powerbank) 型號 (Model)：不詳 (unknown)</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 48%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 48% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electric and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|--|
| 2 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：電子秤 (Scale) 型號 (Model)：KBE-DH8905M-12D</p> | <p>焊料中的鉛濃度過高（測量值按重量計高達 71%）。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求。 The solders have an excessive concentration of lead (measured value up to 71% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品 名(Name)：恆溫杯墊 (Thermostatic coaster) 型號 (Model)：24308</p> | <p>產品中的焊料鎘含量超標（測量值：0.04%（重量））。此外，電纜的塑膠材料含有過量濃度的鄰苯二甲酸二(2-乙基己)酯 (DEHP)和短鏈氯化石蠟(SCCP)(按重量計測量值分別高達 1%和 1.8%)。鎘會生物累積並對環境造成風險。DEHP 對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令（RoHS 2 指令）的要求，也不符合持久性有機污染物 (POP) 法規的要求。 The solders in the product have an excessive concentration of cadmium (measured value: 0.04% by weight). Moreover, the plastic material of the cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP) and short chain chlorinated paraffins (SCCPs) (measured values up to 1% and 1.8% by weight, respectively). Cadmium bio-accumulates and poses a risk to the environment. DEHP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive), nor with the Persistent Organic Pollutants (POP) Regulation.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |



2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|--|---|---|
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : NEXØ 品名(Name) : 電燈 (Electric lamp) 型號 (Model) : DDP000322-4</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 72%)。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 72% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 冷風機 (Air cooler) 型號 (Model) : FS-FFM201-12</p> | <p>產品中的焊料鉛濃度過高。(測量值高達重量的 18%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead. (measured value up to 18% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : INNOVA GOODS 品名(Name) : 修眉器 (Eyebrow trimmer) 型號 (Model) : V0101131</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 83.8%)。鉛對環境構成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求 The solders in the product have an excessive concentration of lead (measured value up to 83.8% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive)</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|--|--|---|
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : Forever 品名(Name) : 移動電源 (Power bank) 型號 (Model) : STB-200 5000 mAh</p> | <p>該產品的焊料鉛濃度過高 (按重量計測量值高達 89%)。該產品的塑膠部件含有過量濃度的鄰苯二甲酸二丁酯 (DBP) 和短鏈氯化石蠟 (SCCP) (按重量計測量值分別高達 0.87%和 1.9%)。鉛對環境構成風險。鄰苯二甲酸鹽對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在, 低濃度時對水生生物有毒, 並在野生動物和人類體內生物累積, 對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。</p> <p>該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求, 也不符合持久性有機污染物 (POP) 法規。</p> <p>The solders of the product have an excessive concentration of lead (measured value up to 89% by weight). Plastic parts of the product have an excessive concentration of dibutyl phthalate (DBP) and short-chain chlorinated paraffins (SCCPs) (measured values up to 0.87% and 1.9% by weight, respectively). Lead poses a risk to the environment. Phthalates poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor does it comply with the Persistent Organic Pollutants (POP) Regulation.</p> | <p>產品不再可用 product no longer available</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 錄音筆 (Voice recording pen) 型號 (Model) : 不詳 (unknown)</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 31%)。鉛對環境構成風險。</p> <p>該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。</p> <p>The solders in the product have an excessive concentration of lead (measured value up to 31% by weight). Lead poses a risk to the environment.</p> <p>The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |



2025 年 1 月電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|--|
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : Otvo 品名(Name) : USB 線 (USB cable) 型號 (Model) : ps2-usb-b, IV-P4S001</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 31%)。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 31% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>邊境拒絕進口 Import rejected at border</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 電動牙刷 (Electric toothbrush) 型號 (Model) : DGU017</p> | <p>電線的塑膠材料含有過量濃度的鄰苯二甲酸二(2-乙基)酯 (DEHP)、鉛和短鏈氯化石蠟 (SCCP) (按重量計測量值分別高達 1.7%、0.34% 和 1.6%)。此外，產品中的焊料鉛含量過高 (按重量計測量值高達 60.9%)。鉛對環境構成風險。DEHP 對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在，低濃度時對水生生物有毒，並在野生動物和人類體內生物累積，對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求，也不符合持久性有機污染物 (POP) 法規的要求。 The plastic material of the cord has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP), lead and short-chain chlorinated paraffins (SCCPs) (measured values up to 1.7%, 0.34% and 1.6% by weight, respectively). Moreover, the solders in the product have an excessive concentration of lead (measured value up to 60.9% by weight). Lead poses a risk to the environment. DEHP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p> | <p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|---|--|--|
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : Butterick's 品名 (Name) : LED 泡棉棒 (LED foam stick) 型號 (Model) : 不詳 (unknown)</p> | <p>產品中的焊料鉛和鎘濃度超標 (按重量計測量值分別高達 84.8% 和 0.16%)。鉛對環境構成風險。鎘會生物累積並對環境造成風險。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。The solders in the product have excessive concentrations of lead and cadmium (measured values up to 84.8% and 0.16% by weight, respectively). Lead poses a risk to the environment. Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 3 | 瑞典 (Sweden) | <p>品牌(Brand) : Provision ISR 品名 (Name) : 電源適配器 (Power supply adaptor) 型號 (Model) : PR-12V1A(EU)</p> | <p>產品中的焊料鉛濃度過高 (測量值: 48.1% (重量))。鉛對環境構成風險。此外, 電纜的塑膠材料中鉛、鄰苯二甲酸二(2-乙基己基)酯(DEHP)、鄰苯二甲酸二丁酯(DBP)和短鏈氯化石蠟 (SCCP)的濃度過高(測量值分別為: 按重量計 0.28%、3.7%、3.2%和 4.5%)。鉛對環境構成風險。鄰苯二甲酸鹽對人類健康和環境構成風險。短鏈氯化石蠟在環境中持續存在, 低濃度時對水生生物有毒, 並在野生動物和人類體內生物累積, 對人類健康和環境構成風險。長時間通過皮膚接觸它們可能會導致癌症。該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求, 也不符合持久性有機污染物 (POP) 法規的要求。The solders in the product have an excessive concentration of lead (measured value: 48.1% by weight). Lead poses a risk to the environment. Moreover, the plastic material of the cable has an excessive concentration of lead, bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP) and short-chain chlorinated paraffins (SCCPs) (measured values: 0.28%, 3.7%, 3.2% and 4.5% by weight, respectively). Lead poses a risk to the environment. The phthalates pose a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |

2025 年 1 月 電子電氣產品召回案例 (歐洲地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|---|--|--|---|
| 4 | 瑞典 (Sweden) | <p>品牌(Brand)：不詳 (unknown) 品名(Name)：放屁機器 (Fart machine) 型號 (Model)：FM-94</p> | <p>產品中的焊料鉛濃度過高 (按重量計測量值高達 74.4%)。鉛對環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 74.4% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p> | <p>從市場撤回 Withdrawal of the product from the market</p> |  |
| 4 | 瑞典 (Sweden) | <p>品牌(Brand)：Feelanture 品名 (Name)：空氣淨化器 (Air purifier) 型號 (Model)：QGW0598246</p> | <p>該產品會產生大量臭氧。高濃度時，臭氧會損害呼吸道。該產品不符合低電壓指令或歐洲標準 EN 60335-2-65 的要求。The product generates high amounts of ozone. At high concentration, ozone can damage the respiratory tract. The product does not comply with the requirements of the Low Voltage Directive nor the European standard EN 60335-2-65.</p> | <p>終端使用者手中召回產品 Recall of the product from end users</p> |  |

2025 年 1 月 電子電氣產品召回案例 (北美地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|--------------|---|--|----------------------------------|--|
| 3 | 美國 (America) | <p>品牌(Brand) : Lexmark 品名(Name) : 印表機 (Printers) 型號 (Model) : MS725dvn , MX725adve</p> | <p>印表機內部的金屬部件可能會脫落，造成火災。 A metal part inside the printer can dislodge, posing a risk of fire.</p> | <p>修理 Repair</p> |  |
| 3 | 美國 (America) | <p>品牌(Brand) : Vornado 品名(Name) : 取暖器 (Room Heaters) 型號 (Model) : TYPE VH2</p> | <p>電源線可能會部分從加熱器外殼上脫落，隨著時間的推移，可能會導致電源線損壞，從而造成觸電和火災危險。 The power cord can partially detach from the heater enclosure, which can lead to cord damage over time, posing electric shock and fire hazards.</p> | <p>替換 Replace</p> |  |
| 4 | 美國 (America) | <p>品牌(Brand) : Teckwe 品名(Name) : 吹風梳子 (Hair Dryer Brushes) 型號 (Model) : 不詳 (unknown)</p> | <p>掌上型吹風機梳子缺乏浸水保護裝置，如果吹風機梳子在插入電源時落入水中，會對消費者造成觸電或觸電危險。美國消費品安全委員會已確定，未配備整體浸水保護裝置的吹風機存在重大產品危險。 The handheld hair dryer brushes lack an immersion protection device, posing an electrocution or shock hazard to consumers if the hair dryer brushes fall into water when plugged in. The CPSC has determined that hair dryers not equipped with the integral immersion protection present a substantial product hazard.</p> | <p>退款 Refund</p> |  |

2025 年 1 月電子電氣產品召回案例 (亞太地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|-------------|--|---|--|---|
| 1 | 臺灣 (Taiwan) | <p>品牌(Brand)：飛利浦 品名(Name)：空氣消毒機 (air sterilizer) 型號 (Model)：UVCA120 W09、UVCA220 W09、UVCA120B Air Disinfection unit、UVCA220B Air Disinfection unit、UVCA110 Air Disinfection uni、UVCA210 Air Disinfection unit</p> | <p>飛利浦 UVC 空氣消毒機二代產品在極端高濕度的環境下工作，可能產生安全疑慮。上述期間產製之飛利浦 UVC 空氣消毒機二代產品在極端高濕度的環境下工作，可能產生安全疑慮。故配合原產地國進行預防性召回作業。</p> | <ol style="list-style-type: none"> 1. 通知專業經銷商立即停止銷售上述批次產品，並就庫存情況與本公司取得聯繫，安排免費的一對一產品替換。 2. 追蹤已售出至終端使用者的全部產品，並協助本公司對仍在使用的產品進行免費的一對一產品替換。 |  |
| 2 | 臺灣 (Taiwan) | <p>品牌(Brand)：Futurelab 未來實驗室 品名(Name)：殺菌除濕機 (Sterilization and dehumidification machine) 型號 (Model)：Stermidi</p> | <p>因電線可被擠入電器內部，恐造成電線或電器內部零件受損，致機體過熱而發生燃燒或延燒之風險。可能造成火災，目前已發生七起事故案例。</p> | <p>保障消費者權益，及避免可能於使用中機體過熱導致機體燃燒或延燒之潛在危險，針對製造日期於 111 年 12 月至 112 年 3 月間或批號 202212080209 之該型號除濕機商品，提供召回換貨服務。</p> |  |
| 4 | 臺灣 (Taiwan) | <p>品牌(Brand)：宏碁智新 品名(Name)：空氣清淨機 (air purifier) 型號 (Model)：AH333-10W</p> | <p>前揭序號之商品零件接合處材質設計，恐有脫落或無法運轉，致商品於使用中機體空轉或過熱之潛在狀況，故自主進行預防性更換新機作業</p> | <ol style="list-style-type: none"> 1.於宏碁智新股份有限公司官網公告序號商品更換作業訊息，受理回收商品，並免費更換新機。 官網連結： https://www.acerpure.com/tw/warranty/notice 2.宏碁智新股份有限公司就已知購買前揭序號商品之消費者進行個別通知商品回收及免費更換新機事宜。 3.宏碁智新股份有限公司敦促持有符合前揭公告序號商品之消費者，請即刻停止使用，並前往宏碁智新股份有限公司全台維修服務據點進行免費更換新機事宜。 4.商品回收暨更換新機諮詢專線：0800-520-555。 |  |

2025年1月電子電氣產品召回案例 (亞太地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|----------------|--|--|--|---|
| 3 | 澳洲 (Australia) | <p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：插入式可攜式壁式加熱器 (Plug-in portable wall heater.)</p> <p>型號 (Model)：不詳 (unknown)</p> | <p>如果加熱器導致牆壁配件、插座或固定線路過熱並著火，則存在嚴重燒傷危險。Risk of serious injury from burns if the heater causes wall fittings, socket outlets or fixed wiring to overheat and catch fire.</p> | <p>消費者應立即停止使用該取暖器。消費者應聯繫 Ozzi Mozzie 安排退貨並獲得全額退款。</p> <p>Consumers should stop using the heater immediately.</p> <p>Consumers should contact Ozzi Mozzie to arrange to return the product for a full refund.</p> |  |
| 3 | 澳洲 (Australia) | <p>品牌(Brand)：Philips</p> <p>品名(Name)：UV-C 消毒空氣機組 G2 (UV-C disinfection air unit G2)</p> <p>型號 (Model)：UVCA220 W01</p> | <p>存在嚴重受傷或死亡以及財產損失的風險。發生了火災。</p> <p>There is a risk of serious injuries or death, and damage to property. Fires have occurred.</p> | <p>立即停止使用本產品並拔掉電源插頭。請聯繫 Signify 安排更換產品。</p> <p>Stop using the product and unplug it from power immediately.</p> <p>Contact Signify to arrange for a replacement product.</p> |  |
| 4 | 澳洲 (Australia) | <p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：鋰電池充電器 (charger for lithium batteries)</p> <p>型號 (Model)：不詳 (unknown)</p> | <p>如果直流充電器過熱，可能會造成嚴重燒傷和財產損失。電壓浪湧可能會損壞連接到直流充電器的敏感設備。</p> <p>Risk of serious burns injuries and property damage if the DC charger overheats. A voltage surge may damage sensitive equipment connected to the DC charger.</p> | <p>立即停止使用直流充電器。請聯繫您當地的 BLA 經銷商以獲取進一步說明。</p> <p>Stop using the DC charger immediately. Contact your local BLA stockist for further instructions.</p> |  |
| 4 | 澳洲 (Australia) | <p>品牌(Brand)：Arlec</p> <p>品名(Name)：電源板 (powerboard)</p> <p>型號 (Model)：PB36-L, PB34UPD</p> | <p>如果電源板著火，則存在嚴重受傷或死亡以及財產損失的風險。事件時有發生。</p> <p>There is a risk of serious injuries or death, and damage to property if the powerboard catches fire. Incidents have occurred.</p> | <p>停止使用電源板並立即拔掉電源插頭。將電源板退回任何 Bunnings 商店即可獲得全額退款。</p> <p>Stop using the powerboard and unplug it from power immediately.</p> <p>Return the powerboard to any Bunnings store for a full refund.</p> |  |

2025 年 1 月 電子電氣產品召回案例 (亞太地區)

| 周 | 通報國家/地區 | 產品 | 危險 | 通報國家採取的措施 | 照片 |
|---|----------------|---|--|--|---|
| 4 | 澳洲 (Australia) | 品牌(Brand)：不詳 (unknown) 品名(Name)：保險絲座 (fuse block) 型號 (Model)：不詳 (unknown) | 如果產品熔化保險絲和保險絲盒並引起火災，則存在嚴重受傷或死亡的危險。 Risk of serious injuries or death if the product melts the fuses and fuse block and causes a fire. | 立即停止使用該產品 ACCC 和維多利亞能源安全局正在與供應商討論適當的補救措施。消費者可以根據消費者保證行使其補救權利，這可能使他們有權獲得全額退款或無缺陷的更換產品。 Stop using the product immediately The ACCC and Energy Safe Victoria are in discussions with the supplier about an appropriate remedy. Consumers can exercise their rights to a remedy in accordance with the consumer guarantees which may entitle them to a full refund or a replacement product that is free of defects. |  |