

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
5	丹麥 (Denmark)	<p>品牌(Brand) : Musiook 品名(Name) : USB 充電器 (USB charger) 型號 (Model) : Musiook2137</p>	<p>SELV (安全特低電壓) 變壓器初級側和次級側之間的爬電距離不足。在安裝和維護/清潔過程中, SELV 電路可能被觸碰, 從而導致觸電。 該產品不符合低電壓指令和歐洲標準 EN 62368-1 的要求。 The creepage distance between primary and secondary side in the SELV (Safety Extra Low Voltage) transformer is insufficient. SELV circuits can be touched during mounting and maintenance/cleaning, leading to electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
2	比利時 (Belgium)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 吹風機梳子 (Hair dryer brush) 型號 (Model) : 5250</p>	<p>該產品中的焊料鉛和鎘含量超標 (實測值分別高達 67% 和 0.56% (重量百分比))。此外, 該產品的塑膠材料中鄰苯二甲酸二(2-乙基己基)酯 (DEHP)、鄰苯二甲酸二異丁酯 (DIBP) 和鄰苯二甲酸二丁酯 (DBP) 的含量也超標 (實測值分別高達 16%、1.5% 和 0.14% (重量百分比))。鉛對環境構成風險, 鎘具有生物累積性, 也會對環境構成風險。鄰苯二甲酸酯可能損害生殖系統, 從而危害健康, 並對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求。 The solders in the product have an excessive concentration of lead and cadmium (measured values up to 67% and 0.56% by weight, respectively). Additionally, the plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), diisobutyl phthalate (DIBP) and dibutyl phthalate (DBP) (measured values up to 16%, 1.5% and 0.14% by weight, respectively). Lead poses a risk to the environment, and cadmium bio-accumulates and poses a risk to the environment. Phthalates may harm the health by causing possible damage to the reproductive system and to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	





2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
1	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：暖氣 (Fan Heater) 型號 (Model)：ML-9001</p>	<p>插頭兩腳之間的距離過短，因此無法提供足夠的接地保護。用戶可能因此觸電。 該產品不符合低電壓指令的要求。 The distance between the pins of the plug is too short and therefore does not provide adequate earthing protection. The user could therefore receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口 Import rejected at border</p>	
1	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：適配器 (Adaptor) 型號 (Model)：CT-15</p>	<p>該變壓器做工粗糙，不符合最小爬電距離和安全距離要求。因此，它可能無法與插座牢固連接。由此，用戶可能接觸到帶電部件並遭受電擊。 該產品不符合低電壓指令的要求。 The transformer is poorly built and does not meet minimum creepage and clearance distances. Therefore, it may not make a secure connection with the plug socket. Due to this, the user may have access to live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口 Import rejected at border 產品銷毀 Destruction of the product</p>	
1	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	<p>品牌(Brand)：BLUEQUE 品名(Name)：美甲吸塵器 (Nail dust collector) 型號 (Model)：BQ858-10</p>	<p>該產品的適配器絕緣不足。用戶可能接觸到裸露的帶電部件而觸電。此外，電源線電阻過大，且產品的火線和地線插腳過短，距離插頭邊緣過近。這可能導致插頭與插座接觸不良，進而造成過熱和火災。 該產品不符合低電壓指令的要求。 The product's adaptor has insufficient insulation. The user could touch accessible live parts and receive an electric shock. Moreover, the mains supply cord has excessive resistance and the live and earthing pins of the product are too short and close to the periphery of the plug. This may prevent the plug from making a secure connection with the socket. This could lead to poor contact, resulting in overheating and causing fire. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>邊境拒絕進口 Import rejected at border</p>	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：不詳 (unknown) 品名(Name)：電源 (Power supply) 型號 (Model)：Q3	<p>該适配器的爬電距離和間隙距離不足。此外，火線和零線插腳過短，且靠近插頭邊緣。這可能導致插頭與插座接觸不良，過熱和/或爆炸，從而引發火災。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The creepage and clearance distances of the adaptor are insufficient. Additionally, the live and neutral pins are too short and close to the periphery of the plug. This could lead to the plug failing to make a secure connection with the socket, overheating and/or exploding, causing a fire.</p> <p>the product does not comply with the requirements of the Low Voltage Directive.</p>	邊境拒絕進口 Import rejected at border	
4	北愛爾蘭 (United Kingdom in respect of Northern Ireland)	品牌(Brand)：Jeneca 品名(Name)：淨水器 (Water filter) 型號 (Model)：XP-01C	<p>該產品的保險絲規格不符，因此無法有效工作。在故障或電流超載的情況下，保險絲可能熔斷，導致插頭起火和/或爆炸。</p> <p>本產品不符合低電壓指令的要求。</p> <p>The product's fuse has an incorrect size and could therefore not operate effectively. Under fault conditions or a surge in current, the fuse could fail, leading to the plug catching fire and/or exploding.</p> <p>This product does not comply with the requirements of the Low Voltage Directive.</p>	線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 邊境拒絕進口 Import rejected at border	
2	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：USB 充電器 (USB charger) 型號 (Model)：EU63	<p>該設備不耐高溫。因此，其外殼可能會變形，導致內部帶電部件暴露。用戶接觸到這些帶電部件可能會導致觸電。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The device is not resistant to high temperatures. Consequently, its casing may deform leaving live parts accessible. The user could touch these live parts, which may lead to an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market	
4	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：ML42N	<p>該產品不具備足夠的電氣絕緣性能。因此，用戶可能因接觸帶電部件而觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。</p> <p>The product does not provide adequate and sufficient electrical insulation. Therefore, the user can receive an electric shock from accessible live parts.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.</p>	從市場撤回 Withdrawal of the product from the market	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
5	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：CL0204	該產品不具備足夠的電氣絕緣性能，使用者可能遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。 The product does not provide adequate and sufficient electrical insulation. The user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	
5	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：4103	該產品不具備足夠的電氣絕緣性能，使用者可能遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。 The product does not provide adequate and sufficient electrical insulation. The user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	
5	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：CL0207	該產品不具備足夠的電氣絕緣性能，使用者可能遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。 The product does not provide adequate and sufficient electrical insulation. The user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	
5	立陶宛 (Lithuania)	品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：CL0209	該產品不具備足夠的電氣絕緣性能，使用者可能遭受電擊。 該產品不符合低電壓指令和歐洲標準 EN 60598 的要求。 The product does not provide adequate and sufficient electrical insulation. The user can receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598.	從市場撤回 Withdrawal of the product from the market	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	西班牙 (Spain)	<p>品牌(Brand) : MTK 品名(Name) : 燈鏈 (Lighting chain) 型號 (Model) : TW1416</p>	<p>該產品存在燙傷風險，因為導體的橫截面積過小。這可能導致過熱，進而引發火災。 該產品不符合低電壓指令和歐洲標準 EN 60598-2-20 的要求。 The product poses a risk of burns, since the cross-section of the conductors is too small. This could accumulate too much heat energy and catch fire. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 60598-2-20.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures</p>	
1	克羅埃西亞 (Croatia)	<p>品牌(Brand) : Switch ON 品名(Name) : 電動咖啡研磨 (Electric coffee grinder) 型號 (Model) : IAN 460907-2401 SOKME 180 C1</p>	<p>電路間的爬電距離和安全距離不足，且不符合絕緣要求。這可能導致用戶因接觸帶電部件而觸電。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 60335-2。 There is insufficient creepage and clearance distance between circuits, and it does not meet required insulation requirements. This can lead to the user receiving an electric shock from accessible live parts. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and 60335-2.</p>	<p>禁止銷售產品及任何附帶措施 Ban on the marketing of the product and any accompanying measures 從市場撤回 Withdrawal of the product from the market</p>	
4	法國 (France)	<p>品牌(Brand) : Vevor 品名(Name) : 扣式電池 (Button batteries) 型號 (Model) : CR2016 3V</p>	<p>包裝並非兒童安全包裝，因此鈕扣電池很容易被兒童拿到。兒童可能會將電池放入口中，導致窒息。如果誤食鈕扣電池，也可能對兒童的消化系統造成損害。 本產品不符合通用產品安全法規 (GDPR) 和歐洲標準 EN 60086-4。 The packaging is not childproof and therefore the button batteries are easily accessible to children. A child may put them in the mouth, and choke. The button batteries could also cause damage to the child's gastrointestinal tract if they are ingested. This product does not comply with the General Product Safety Regulation nor with the European standard EN 60086-4.</p>	<p>線上市場刪除了該產品清單 Removal of this product listing by the online marketplace 終端使用者手中召回產品 Recall of the product from end users</p>	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
5	法國 (France)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：煮蛋器 (Egg cooker) 型號 (Model)：7 eggs 1 once</p>	<p>該電器的金屬部件（例如外殼或外部部件）與帶電部件之間的接觸保護不足。此外，該電器不夠堅固，在受到撞擊或跌落時容易損壞，導致帶電部件裸露，從而可能造成觸電事故。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-23。 The accessible metal parts of the appliance (such as the cover or external parts) are not sufficiently protected from the live electrical parts. Moreover, the appliance is not sufficiently robust and, in case of impact or fall, could easily break, leaving the live parts accessible, which could lead to an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-23.</p>	<p>警告消費者風險 Warning consumers of the risks 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
5	法國 (France)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：迷你熨斗 (Mini Iron) 型號 (Model)：ZF688</p>	<p>由於絕緣不足，金屬部件和電線固定不牢固。因此，用戶可能接觸到帶電部件並觸電。此外，電源線過短，限制了操作人員的活動範圍，並可能導致電纜受力過大，使電烙鐵掉落，造成用戶燙傷或引發火災。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-23。 Due to insufficient insulation, the metal parts and the electrical wires are not fixed securely. The user can therefore access live parts and receive an electric shock. Moreover, the power cable is too short, which limits the movement and could stress the cable, leading the iron to fall, causing burns to the user or a fire. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-23.</p>	<p>警告消費者風險 Warning consumers of the risks 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	

2026年1月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
5	法國 (France)	品牌(Brand)：不詳 (unknown) 品名(Name)：吹風機 (Hair dryer) 型號 (Model)：XR-8818	<p>該產品絕緣不足。因此，用戶可能接觸到帶電部件，並可能遭受電擊。此外，該電器無法提供標稱功率，超載時可能導致過熱，進而造成用戶燙傷。而且，內部電纜僅通過脆弱的焊接固定。隨著時間的推移，電纜可能脫落，使用戶能夠接觸到帶電部件。這可能導致用戶觸電或因短路而引發火災。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-23。</p> <p>The product is not adequately insulated. The user has therefore access to live parts and could receive an electric shock. Additionally, the appliance does not deliver the announced power, which could lead to overheating in the event of overload. This could cause burns to the user. Moreover, an internal electrical cable is held in place only by a fragile weld. The cable may come off over time, making live parts accessible. This could cause the user to receive an electric shock or a fire due to a short circuit.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-23.</p>	<p>線上市場刪除了該產品清單</p> <p>Removal of this product listing by the online marketplace</p>	
5	法國 (France)	品牌(Brand)：*KEMEI* 品名(Name)：直發器 (Hair straightener) 型號 (Model)：KM-957	<p>產品中的帶電導線防護不足。此外，帶電導線與可觸及部件之間的空間過小。帶電部件可能暴露在外，用戶可能因此觸電。</p> <p>該產品不符合低電壓指令的要求。</p> <p>A live electrical wire in the product is not sufficiently protected. Moreover, the space between the live wire and the accessible parts is too small. Live parts may become accessible, and the user could receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>線上市場刪除了該產品清單</p> <p>Removal of this product listing by the online marketplace</p>	

2026年1月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
5	法國 (France)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：直發器 (Hair straightener) 型號 (Model)：Hair Dryer - AC110V - AC240V - 50Hz</p>	<p>該產品絕緣性能不足。帶電部件與用戶可觸及部件之間的防護措施不足，尤其是出風口的金屬格柵。格柵與雙金屬開關之間以及格柵與加熱元件之間的安全距離不足。因此，用戶可能接觸到帶電部件並觸電，尤其是在潮濕或有冷凝水的情況下。 該產品不符合低電壓指令的要求。 The product has insufficient insulation. Live parts are not sufficiently protected from parts accessible to the user, in particular the metal grille of the air outlet. The safety distances between the grille and the bimetallic switch and between the grille and the heating element are insufficient. The user can therefore access live parts and receive an electric shock, especially in the case of moisture or condensation. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>警告消費者風險 Warning consumers of the risks 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
5	法國 (France)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：SL-300L</p>	<p>該產品不具備防潮功能。因此，水可能滲入產品內部，導致觸電。此外，產品可能過熱，從而引發火災。 該產品不符合低電壓指令的要求。 The product is not protected against moisture. Consequently, water could penetrate the product and cause an electric shock. Moreover, the product may overheat, leading to a risk of fire. The product does not comply with the requirements of the Low Voltage Directive.</p>	<p>警告消費者風險 Warning consumers of the risks 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
5	法國 (France)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：燈鏈 (Lighting chain) 型號 (Model)：不詳 (unknown)</p>	<p>該產品會在聯網設備之間造成電磁干擾。這可能會通過電壓和電流畸變影響其他電氣設備的安全和正常運行。 該產品不符合電磁兼容性指令 (EMC) 的要求，也不符合歐洲標準 EN 55015。 The product causes electromagnetic disturbance between various network-connected devices. This can affect the safe and proper functioning of other electrical equipment through voltage and current distortions. The product does not comply with the requirements of the Electromagnetic Compatibility Directive nor with the European standard EN 55015.</p>	<p>警告消費者風險 Warning consumers of the risks 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	

2026年1月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
1	波蘭 (Poland)	品牌(Brand) : Rangers 品名(Name) : 逆變焊機 (Inverter welder) 型號 (Model) : MMA-300A RS-1457	<p>電源線的橫截面積過小，且長度過短。電線可能過熱，導致絕緣層損壞，使帶電部件暴露在外。用戶可能觸碰到帶電部件而觸電。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60974-1。</p> <p>The cross-sectional area of the power supply cable is too low. Moreover, the power supply cable is too short. The wires may overheat and cause the insulation to become damaged making live parts accessible. The user could touch live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive, nor with the European standard EN 60974-1.</p>	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks	
2	波蘭 (Poland)	品牌(Brand) : GTV 品名(Name) : 電源終端 (Power supply terminal) 型號 (Model) : XLT-1FAC68-00 XLT-1FAC69-10	<p>保護導體的保護不足，可能導致保護性接地中斷。因此，用戶可接觸到帶電部件，從而可能遭受電擊。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The protection of the protective conductor is insufficient, which can lead to protective earth interruption. Live parts are therefore accessible to the user, who can receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	
2	波蘭 (Poland)	品牌(Brand) : GTV 品名(Name) : 電源終連接器 (Power supply connector) 型號 (Model) : XLT-1FAC19-00 XLT-1FAC24A-10 XLT-1FAC33-00 XLT-1FAC34-10	<p>保護導體的保護不足，可能導致保護性接地中斷。因此，用戶可接觸到帶電部件，從而可能遭受電擊。</p> <p>該產品不符合低電壓指令的要求。</p> <p>The protection of the protective conductor is insufficient, which can lead to protective earth interruption. Live parts are therefore accessible to the user, who can receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	
4	波蘭 (Poland)	品牌(Brand) : 不詳 (unknown) 品名(Name) : 水泵 (Water pump) 型號 (Model) : RK-4160 VP10A	<p>由於電纜接地不良以及電源線橫截面積過小，該產品存在使用者觸電的風險。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2。</p> <p>Due to inadequate grounding of the cable and the cross-section area of the power cord, the product poses a risk of electric shock to the user.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2.</p>	從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
1	波蘭 (Poland)	<p>品牌(Brand) : Rangers 品名(Name) : 逆變焊機 (Inverter welder) 型號 (Model) : MMA-300A RS-1457</p>	<p>電源線的橫截面積過小，且長度過短。電線可能過熱，導致絕緣層損壞，使帶電部件暴露在外。用戶可能觸碰到帶電部件而觸電。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60974-1。 The cross-sectional area of the power supply cable is too low. Moreover, the power supply cable is too short. The wires may overheat and cause the insulation to become damaged making live parts accessible. The user could touch live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive, nor with the European standard EN 60974-1.</p>	<p>從市場撤回 Withdrawal of the product from the market 警告消費者風險 Warning consumers of the risks</p>	
4	斯洛伐克 (Slovakia)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 數位體溫計 (Digital thermometer) 型號 (Model) : TP101</p>	<p>該產品中的焊料鉛含量超標 (實測值最高達 36.8% (重量百分比)) 和鎘含量超標 (實測值最高達 0.104% (重量百分比))。鉛和鎘會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 36.8 % by weight) and cadmium (measured value up to 0.104 % by weight). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks</p>	
5	斯洛伐克 (Slovakia)	<p>品牌(Brand) : Babyverse 品名(Name) : 直發器 (Hair straightener) 型號 (Model) : BA-1292</p>	<p>由於電源線橫截面積不足，該產品存在使用者觸電的風險。此外，由於過熱，導體絕緣層可能著火。 該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2-23。 Due to inadequate cross-section area of the power cord, the product poses a risk of electric shock to the user. Moreover, due to overheating, the insulation of the conductors could ignite. The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-23.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 警告消費者風險 Warning consumers of the risks</p>	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	斯洛維尼亞 (Slovenia)	品牌(Brand) : ROYALSTAR 品名(Name) : 電烤箱 (Electric Oven) 型號 (Model) : YX-11	<p>該產品缺少必要的安全聲明和使用說明。這可能導致使用者不當使用該設備，並造成觸電危險。此外，該產品的額定電壓和額定輸入功率不足，可能導致超載，其基本絕緣可能受損，造成溫度升高和接地不良。這可能導致用戶觸電或接觸過熱的可觸及表面而燙傷。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2。</p> <p>The product lacks the required safety statements and instructions for use. This could lead to inappropriate use of the appliance and the user receiving an electric shock. Moreover, the product has inadequate rated voltage and rated input power which can lead it to overload, and its basic insulation can be damaged and cause high temperature rises and non-reliable earth connection. This can lead to the user receiving an electric shock or touching the overheated accessible surfaces and suffering burns.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2.</p>	線上市場刪除了該產品清單 Removal of this product listing by the online marketplace	
1	愛爾蘭 (Ireland)	品牌(Brand) : RUGGED 品名(Name) : 電源延長線 (Extension lead) 型號 (Model) : 不詳 (unknown)	<p>由於製造缺陷，該產品可能過熱。因此，電纜在負載下可能熔化，從而造成火災和燒傷風險。</p> <p>該產品不符合低電壓指令的要求。</p> <p>Due to a manufacturing fault, the product may overheat. As a result, the cable may melt under load, which could create a risk of fire and burns.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	
3	愛爾蘭 (Ireland)	品牌(Brand) : GoodHome 品名(Name) : 電熱毯 (Electric blanket) 型號 (Model) : Saturnia	<p>電容器存在缺陷，可能過熱。這會導致溫控器變形熔化，從而增加火災風險，並使帶電部件暴露於用戶。用戶接觸到這些帶電部件可能會觸電。</p> <p>該產品不符合低電壓指令的要求。</p> <p>An electrical capacitor is defective and may overheat. This could cause the heat controller to deform and melt which increases the risk of fire and exposing live parts to the user. The user could touch the accessible live parts and receive an electric shock.</p> <p>The product does not comply with the requirements of the Low Voltage Directive.</p>	從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users	

2026 年 1 月電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
1	瑞典 (Sweden)	<p>品牌(Brand) : IZOXIS 品名(Name) : 夜燈 (Night lamp) 型號 (Model) : ZN01</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 0.86% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 0.86% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
2	瑞典 (Sweden)	<p>品牌(Brand) : 不詳 (unknown) 品名(Name) : 移動電源 (Powerbank) 型號 (Model) : MW-20230120</p>	<p>該產品中的焊料鉛含量超標 (實測值最高達 55.1% (重量比))。此外，電纜中的塑膠材料鄰苯二甲酸二丁酯 (DBP) 含量超標 (實測值最高達 3.85% (重量比))。該產品還含有過量的短鏈氯化石蠟 (SCCPs) (實測值最高達 0.8% (重量比))。鉛對環境構成風險。DBP 對人類健康和環境構成風險。SCCPs 會在環境中持久存在，低濃度下即可對水生生物產生毒性，並在野生動物和人體內生物累積，對人類健康和環境構成風險。長期經皮膚接觸可能導致癌症。 該產品不符合《關於限制在電氣和電子設備中使用某些有害物質的指令》(RoHS 2 指令) 和《持久性有機污染物 (POP) 條例》的要求。 The solders in the product have an excessive concentration of lead (measured value up to 55.1% by weight). In addition, plastic material in the cables contain excessive concentrations of dibutyl phthalate (DBP) (measured value up to 3.85% by weight). The product also has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 0.8 % by weight). Lead poses a risk to the environment. DBP poses a risk to human health and the environment. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive) nor with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	瑞典 (Sweden)	<p>品牌(Brand) : Velamp 品名(Name) : 露營燈 (Camping lantern) 型號 (Model) : IC207/PX21501</p>	<p>該產品中的焊料鉛含量過高 (實測值高達 83.3% (重量比)) 。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up 83.3% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
2	瑞典 (Sweden)	<p>品牌(Brand) : AiQUE 品名(Name) : 溫度計 (Thermometer) 型號 (Model) : AD802/UX-A-02</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 67% (重量比)) 。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 67% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
2	瑞典 (Sweden)	<p>品牌(Brand) : FL-Tronics 品名(Name) : 溫度計 (Thermometer) 型號 (Model) : 250030/1097565</p>	<p>該產品的塑膠材料中鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 的含量過高 (實測值最高達 47% (重量比)) 。這種鄰苯二甲酸酯可能危害使用者健康，甚至可能損害生殖系統。 該產品不符合歐盟委員會關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求。 The plastic material of the product contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 47% by weight). This phthalate may harm the health of users, possibly causing damage to the reproductive system. The product does not comply with the requirements of the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	


2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
3	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：露營燈 (Camping lantern) 型號 (Model)：38-21515 RD239A</p>	<p>該產品中的焊料鉛含量過高 (實測值最高達 64.9% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 64.9% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
3	瑞典 (Sweden)	<p>品牌(Brand)：不詳 (unknown) 品名(Name)：LED 燈 (LED lights) 型號 (Model)：14280_CZ</p>	<p>該產品中的焊料鉛含量超標 (實測值：68.9% (重量比))。鉛會對環境造成危害。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value: 68.9% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).</p>	<p>從市場撤回 Withdrawal of the product from the market</p>	
5	瑞典 (Sweden)	<p>品牌(Brand)：Highlands International 品名(Name)：發電機 (Power generator) 型號 (Model)：103014</p>	<p>該產品中的焊料鉛含量超標 (實測值最高達 78.8%重量比)。此外，線纜中的塑膠材料鄰苯二甲酸二(2-乙基己基)酯 (DEHP) 含量超標 (實測值最高達 24.58%重量比)。鉛對環境構成風險，而 DEHP 對人類健康和環境構成風險。 該產品不符合關於限制在電氣和電子設備中使用某些有害物質的指令 (RoHS 2 指令) 的要求。 The solders in the product have an excessive concentration of lead (measured value up to 78.8% by weight). In addition, the plastic material in the cords and the cables has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 24.58% by weight). Lead poses a risk to the environment, whereas DEHP poses a risk to human health and the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>禁止銷售 Stop of sales</p>	

2026 年 1 月 電子電氣產品召回案例 (歐洲地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	德國 (Germany)	<p>品牌(Brand) : MICHELINO 品名(Name) : 電水壺 (Electric kettle) 型號 (Model) : 74355</p>	<p>在進口商銷售的類似型號水壺中，檢測出短鏈氯化石蠟 (SCCPs) 濃度過高。進口商無法排除該產品 SCCPs 濃度過高的可能性。SCCPs 會在環境中持久存在，即使低濃度也會對水生生物造成毒害，並在野生動物和人體內生物累積，對人類健康和環境構成威脅。</p> <p>該產品不符合持久性有機污染物 (POPs) 法規的要求。</p> <p>In similar models of kettle by the importer, excessive concentration of short chain chlorinated paraffins (SCCPs) were found. The importer cannot rule out that this product does not have an excessive concentration of SCCPs. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. The product does not comply with the Persistent Organic Pollutants (POP) Regulation.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	
3	德國 (Germany)	<p>品牌(Brand) : OSRAM 品名(Name) : 燈泡 (Light bulb) 型號 (Model) : AC45702 AC45703</p>	<p>燈泡的擴散器容易脫落，露出帶電部件。用戶接觸這些帶電部件可能會觸電。</p> <p>該產品不符合低電壓指令和歐洲標準 EN 62560 的要求。</p> <p>The bulb's diffuser can easily detach, exposing live parts. The user can touch these live parts and receive an electric shock. The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62560.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users 線上市場刪除了該產品清單 Removal of this product listing by the online marketplace</p>	
3	德國 (Germany)	<p>品牌(Brand) : POTYYH 品名(Name) : 電烤麵包爐 (Electric toaster) 型號 (Model) : LV-556</p>	<p>該產品接地保護和絕緣性能不足，使用者可能因此觸電。此外，產品金屬表面在使用過程中可能過熱，造成燙傷風險。</p> <p>該產品不符合低電壓指令的要求，也不符合歐洲標準 EN 60335-1 和 EN 60335-2。</p> <p>The product does not provide adequate earthing protection and sufficient insulation. The user could therefore receive an electric shock. Moreover, the metal surface of the product may overheat while in use. Consequently, this poses a risk of burns for the user.</p> <p>The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2.</p>	<p>從市場撤回 Withdrawal of the product from the market 終端使用者手中召回產品 Recall of the product from end users</p>	

2026 年 1 月 電子電氣產品召回案例 (北美地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	美國 (America)	品牌(Brand) : Isla Rae 品名(Name) : 磁吸式無線充電器 (Magnetic Wireless Chargers) 型號 (Model) : RM5PBM	充電器在使用過程中可能會爆炸，造成火災和燒傷危險。 The chargers can explode while in use, posing a fire and burn hazard.	退款 Refund	
3	美國 (America)	品牌(Brand) : Frigidaire-brand 品名(Name) : 迷你冰箱 (Minifridges) 型號 (Model) : EFMIS121	迷你冰箱內部的電子元件可能會短路並引燃周圍的塑膠外殼，造成火災和燒傷危險。 The minifridges' internal electrical components can short circuit and ignite the surrounding plastic housing, posing fire and burn hazards.	退款 Refund	
3	美國 (America)	品牌(Brand) : Energizer 品名(Name) : 大功率指示燈 (Large Power Indicator Lantern) 型號 (Model) : BGAAL9	燈籠中安裝的鋰離子電池可能會過熱，對消費者構成燙傷危險。 The lithium-ion batteries installed in the lanterns can overheat, posing a burn hazard to consumers.	退款 Refund	
3	美國 (America)	品牌(Brand) : HEZI 品名(Name) : 電源插座 (Power Strips) 型號 (Model) : 不詳 (unknown)	這些電源插座採用未接地的金屬外殼，通電後會造成觸電危險，導致嚴重傷害甚至死亡。 The power strips have an ungrounded metal enclosure that poses an electrocution hazard if energized, resulting in serious injury or death.	退款 Refund	
4	美國 (America)	品牌(Brand) : Topkay 品名(Name) : 手電筒 (Torch Lighters) 型號 (Model) : 不詳 (unknown)	被召回的打火機違反了多用途打火機的強制性標準，因為它們沒有必要的兒童安全裝置，存在因火災和燒傷而造成嚴重傷害或死亡的風險。 The recalled lighters violate the mandatory standard for multipurpose lighters because they do not have the required child-resistant mechanisms, posing a risk of serious injury or death from fire and burn hazards.	退款 Refund	

2026 年 1 月 電子電氣產品召回案例 (亞太地區)

周	通報國家/地區	產品	危險	通報國家採取的措施	照片
2	澳洲 (Australia)	<p>品牌(Brand)：不詳 (unknown)</p> <p>品名(Name)：插入式可攜式壁式加熱器 (Plug-in portable wall heater.)</p> <p>型號 (Model)：不詳 (unknown)</p>	<p>如果加熱器導致牆壁配件、插座或固定線路過熱並著火，則存在嚴重燒傷危險。Risk of serious injury from burns if the heater causes wall fittings, socket outlets or fixed wiring to overheat and catch fire.</p>	<p>消費者應立即停止使用該取暖器。 消費者應聯繫 Ozzi Mozzie 安排退貨並獲得全額退款。 Consumers should stop using the heater immediately. Consumers should contact Ozzi Mozzie to arrange to return the product for a full refund.</p>	
5	韓國(Korea)	<p>品牌(Brand)：주식회사 레칸</p> <p>品名(Name)：鋰電池 (Lithium-ion Battery/Battery)</p> <p>型號 (Model)：RLB-18V-LI60 / 전지</p>	<p>電池充電器連接後立即發生內部短路可能導致火花、火焰和煙霧，並可能因火災而損壞周圍的設施和建築物。尤其是在商業和公共設施等多功能場所，火災有可能升級為人員傷亡。 Internal short circuits immediately after connecting the battery charger can cause sparks, flames, and smoke, and there is a risk of damage to surrounding fixtures and buildings due to fire. In particular, there is a possibility that multi-use spaces such as commercial and public facilities will escalate to human casualties.</p>	<p>使用此類電池的消費者應立即停止使用並充電。從充電器中取出後，請將其存放在安全的地方，並根據經銷商網站上的召回通知 (https://buly.kr/3u4Lsx7)、召回通知短信以及客戶中心提供的程式進行領取、更換或退款。 Consumers with such batteries should stop using and charging them immediately. After removing it from the charger, store it in a safe place, and proceed with collection, exchange, or refund according to the recall notice (https://buly.kr/3u4Lsx7) on the dealer's website, the recall notice text message, and the procedures provided through the customer center.</p>	